


LYCOMING ENGINES  
652 OLIVER STREET  
WILLIAMSPORT, PA 17701  
P +001 570.323.6181  
F +001 570.327.7066

---

## Aftermarket Engine Price List

---



AVAILABLE FROM AUTHORIZED  
LYCOMING DISTRIBUTORS

**Effective January 1, 2012**

*(All prices subject to change without notice)*

**LYCOMING**

LYCOMING.COM

© 2010 Avco Corporation. All Rights Reserved.

**Prices:** in US-Dollar, ex works LYCOMING, USA

**Freight:** fixed prices for freight USA – Germany, **incl. core return**

Type 235 - 320	US\$	1.700,--
Type 360	US\$	1.900,--
Type 540 - 541	US\$	2.100,--

**Warranty:** original LYCOMING (please see below)

**Accessories:** per original LYCOMING specification

**Payment:** in US\$ or EURO at current exchange rate at date of factura, or as agreed with order

**Deposit:** complete, assembled and in running condition core engine must be returned to us within 30 days as per LYCOMING Core Return Policy (please see below)

(Furthermore please pay attention to our current Delivery & Payment Terms)

**Office hours: Monday to Friday from 8.00 a.m. to 6.00 p.m.**



**GLOBAL AVIATION + PIPER PARTS GMBH**

Flughafen Kassel  
34379 Calden / Germany

0049 (0) 5674 704 - 23  
0049 (0) 5674 704 - 24  
0049 (0) 5674 704 - 27  
0049 (0) 5674 704 - 28

Patrick Dürrbaum  
Manfred Lendbradl  
Peter Heiter  
Sandra Weitkämper

0049 (0) 5674 704 - 44

FAX

**email:** [parts@globalaviationparts.de](mailto:parts@globalaviationparts.de)

**Internet:** <http://www.globalaviationparts.de>

**To: All Lycoming Exchange Engine customers**

**Subject: Your Engine Core Model:** \_\_\_\_\_ **Engine Core S/N:** \_\_\_\_\_

**TSN:** \_\_\_\_\_

**Aircraft matriculation:** \_\_\_\_\_

Dear Valued Customer,

The following information is provided to you to give you a better understanding of the current Lycoming engine Core Return Policy and its processing in general. It is in any case valid for your a.m. engine core.

**PLEASE VERIFY THAT YOUR A.M. CORE MEETS LYCOMING'S ACCEPTANCE CRITERIA AS FOLLOWS:**

1. Core return must be in time. That means the core return to Piper Generalvertretung Deutschland AG has to be done within 60 days after engine invoice date for overhauled engine through Piper Generalvertretung Deutschland AG. Delay will cause a late core charge of USD 300,00 , which will be invoiced to you for every belated month.
2. The engine core being returned has to be the same model and specification than the purchased one.
3. The engine core has to be returned in **complete** and **running condition**, what means in detail:
  - Engine must be **assembled!**
  - Engine must be **active** (operated and serviced within the last 12 months!)
  - Engine has to be **in operable condition** and **must have the valid Engine Data Plate** firmly attached!
  - Crankcase must be serviceable or deduction shall apply!
  - Crankshaft must be serviceable or deduction shall apply!

Exchange engine cores become the property of Lycoming.

Lycoming reserves the right to accept or reject any engine core returned.

Cores will be inspected in accordance with Lycoming manufacturing specifications.

Lycoming's determination as to parts serviceability shall be final.

Parts that do not pass inspection will be scrapped.

Lycoming will not accept additional parts to replace unserviceable parts.

In reverse, the above listing of details is to be interpreted that in case of an engine order on exchange basis with return of an incomplete, disassembled, inactive or inoperable core the following amounts will be charged by Lycoming:

**The Core value itself (as per Lycoming Price List),  
furthermore a 'core cancellation fee' of usually USD 2.400,00  
as well as the balance between overhauled and rebuilt engine prices  
(pricing plus VAT – where applicable).**

---

I have been informed by Piper Generalvertretung Deutschland AG of the terms and conditions governing the Lycoming Exchange Core Policy and agree to adhere to all criteria of the policy. In the event that I fail to abide by the policy, I agree to cover all damages which Piper Generalvertretung Deutschland AG incurs as a result of my default.

I understand that late charges will apply for any core that is returned after 60 days at a rate of USD 300,00 per month.

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_

## **SALES TERMS AND CONDITIONS**

1. All prices are subject to change without notice.
2. All prices are Ex Works Williamsport, PA, U.S.A.
3. Engine availability subject to change without notice.
4. New Exchange or New Outright Engines - New engines may be purchased without an exchange engine core (outright) or on an exchange basis. New Outright list price is calculated by simply multiplying the published new exchange list price by 1.2.
5. Rebuilt Exchange or Rebuilt Outright Engines - Rebuilt engines are normally purchased on an exchange basis. Occasionally, upon request Lycoming Engines may approve the sale of a Rebuilt engine on an outright basis; however, only Lycoming Engines has this authority, prior written authorization is required. Rebuilt Outright list price, when approved is usually the same as the published new exchange list price.
6. Overhauled Exchange Engines - Overhauled engines may only be purchased on an exchange basis.
7. Engine mounting brackets are not furnished on rebuilt and overhauled engines.
8. Orders for rebuilt and overhauled engines are subject to the availability of core engines.
9. Engines sold on an exchange basis are shipped prior to the receipt of the exchange engine core and will be billed a core charge as listed on the applicable engine price list.
10. Exchange engine core prices are NET and are not subject to any discount.
11. All exchange engine cores must comply with Lycoming Engines exchange engine core policy as communicated in the latest edition of Lycoming Service Letter 250 and must be returned to the Lycoming Engines factory accompanied by a completed Factory Return Authorization Worksheet (Form 2500)
12. All engines returned for custom overhaul or custom rebuild must comply with Lycoming Engines exchange engine core policy as communicated in the latest edition of Lycoming Service Letter 250.
13. Bills of lading for exchange engine cores should identify the shipment as "INTERNAL COMBUSTION ENGINE" and the value should be declared "NOT TO EXCEED \$5.00 PER POUND" in order to obtain the lowest freight rate.
14. Lycoming Engines will not be responsible for non-engine accessories returned on the exchange engine core. (Vacuum pumps, fittings, hydraulic pumps, governors, hoses, etc.)
15. Replacement engines for Aerobatic aircraft installation may not include the aerobatic kit, hoses or fittings.
16. Generators are no longer available for those models originally supplied with a generator. If a LYCOMING ENGINES generator was supplied with the original engine, DO NOT RETURN THE GENERATOR WITH THE EXCHANGE ENGINE CORE.
17. Regulators, relays and starter switches are no longer available from Lycoming Engines.



# Factory Overhauled Engines.

**A time-continued engine capable of running to its recommended TBO ... again.**

**There is no better overhaul for a Lycoming engine than a genuine factory overhaul.**

**After all, we built the original. Our parts are genuine Lycoming, our labor is genuine Lycoming and backed by over 70 years of experience, building piston aircraft engines for more than half the general aviation aircraft in the world.**

During a factory overhaul, existing engine parts from similar or compatible engines that meet Lycoming's service allowable limits are reused where appropriate.

There is however, an automatic "throw it away and replace it" policy for any part that doesn't measure up.

And, a number of specified critical parts are replaced with new parts, no questions asked.

It's important to know also, that with a factory overhaul, the price you're quoted is the price you'll pay ... providing the crankcase and crankshaft are usable.

There are no "we didn't know about that until we opened it up" surprises.

Any product improvements developed by Lycoming for the engine after it was originally produced, will automatically be incorporated during the overhaul process,

at no additional cost to you. The engine will comply with the latest configuration required by all Lycoming Service Bulletins and all FAA Airworthiness Directives at the time of overhaul.

All Lycoming overhauled engines get the standard accessories included when the engine was new. The overhauled price includes the fuel metering system, ignition system and starter. Where applicable, the turbocharging system (including exhaust system), alternator, engine-driven fuel pump and provisions for pneumatic and hydraulic pump drives are included.

The engine is reassembled with totally new cylinder assemblies and many other new Lycoming parts not normally installed by other overhaulers.

There's another benefit to a genuine Lycoming factory overhaul: The time-continued engine is capable of running to its recommended TBO again ... backed by a factory warranty for a full year from the time you fire it up, regardless of the number of hours flown. Parts and labor. And, your warranty will be honored at any authorized Textron Lycoming Distributor worldwide.

**Here's what you get with a genuine Textron Lycoming factory overhaul that you don't get everywhere else.**

**New** cylinder heads & barrels.

**New** pistons & rings.

**New** piston pins & plugs.

**New** guides, seats & springs.

**New** intake and exhaust valves.

■ Automatic replacement of all items listed in our Service Bulletin #240: from oil hoses and seals... to bearing inserts and counter-weight bushings.

■ Automatic replacement of any and all parts not meeting Lycoming's critical inspection standards.

■ A full, one-year Textron Lycoming warranty with world-wide support.



# "Zero-time rebuilt" Engines

**The zero-time, high quality,  
cost effective alternative.**

**Only  
the factory can  
"zero-time rebuild"  
a Lycoming engine.**

**The immediate  
benefit of a  
"zero-time rebuild"  
is: the engine  
gets a brand new  
log book.**

Then - just as with a new Lycoming - the rebuilt engine is tested to factory specifications to be sure it's up to the performance standards of a new engine.

When your rebuilt Lycoming is installed, it will have a new "zero-time" log book provided by the factory, and the same warranty and recommended TBO as a new Lycoming.

As an added long-term benefit, your rebuilt engine will be capable of being overhauled when it reaches TBO. And the factory warranty will be honored at any authorized Textron Lycoming Distributor worldwide.

During the rebuilding process, those parts specified for automatic removal are replaced with brand-new Lycoming parts. Any reusable parts are inspected for conformity with new part tolerances or limits.

The engine is then reassembled with all new cylinder assemblies, including barrels, heads, pistons, rings, piston pins and plugs, intake and exhaust valves, springs, guides, seats and gaskets.

## **Here's what you get with a genuine Textron Lycoming "zero-time rebuilt" engine.**

**New** cylinder heads & barrels.

**New** pistons & rings.

**New** piston pins & plugs.

**New** guides, seats & springs.

**New** exhaust valves.

**New** intake valves.

■ Automatic replacement of all items listed in our Service Bulletin #240: from oil hoses and seals... to bearing inserts and counter-weight bushings.

■ Automatic replacement of any and all parts not meeting new engine tolerances.

■ The same factory warranty as a new Lycoming engine with world-wide support.

■ New "zero-time" log book.

■ Same recommended TBO as a new Lycoming.

## Lycoming Engine Sales Program Comparison

	Lycoming Factory Rebuilt at Overhaul Price Program	Lycoming Loyalty Program
<b>Promotion Benefits:</b>	Purchase Factory Rebuilt Engines at Factory Overhaul prices! Saving up to \$5,000.00	Upfront price discounts of up to \$1,900.00 on a Factory New, Rebuilt or Overhauled engine.
<b>Price Discounts:</b>	Rebuilt Engines discounted to corresponding Overhaul price.	Discounted according to the matrix below. Determined by the type of engine purchased and the heritage of the exchange engine core when it last shipped from the Factory.
<b>Exchange Engine Core Requirements:</b>	Factory New Only. Exchange engine core must be "First Run" and not have been overhauled or rebuilt since shipping from the Factory as a new engine. Exchange engine core must have been placed in service on or after January 1 <sup>st</sup> , 1990. Exchange engine core must comply with the Lycoming Engines exchange engine core policy as communicated in the latest edition of Lycoming Service Letter 250.	Factory New, Rebuilt or Overhauled. Exchange engine core must not have been field overhauled since it last shipped from the Factory. Exchange engine core must have been placed in service on or after January 1 <sup>st</sup> , 1990. Exchange engine core must comply with the Lycoming Engines exchange engine core policy as communicated in the latest edition of Lycoming Service Letter 250.
<b>Additional Program Conditions:</b>	Exchange engine core values are listed in the "New Exchange Engine Core Values" table. <b>Program discounts cannot be combined with the Fleet Rebate program</b>	Exchange engine core values are listed in the "Select Exchange Engine Core Values" table. <b>Program discounts cannot be combined with the Fleet Rebate program</b>

**Lycoming Factory Loyalty Program Discount Table**

		Purchasing		
		New	Rebuilt	Overhaul
<b>CORE CONDITION</b>		<b>4 Cylinder</b>		
	New	\$1,200	N/A	\$1,200
	Rebuilt	\$800	\$800	\$800
	Overhaul	\$600	\$600	\$600
		<b>4 Cylinder Turbo</b>		
	New	\$1,300	N/A	\$1,300
	Rebuilt	\$900	\$900	\$900
	Overhaul	\$800	\$800	\$800
		<b>6 Cylinder</b>		
	New	\$1,800	N/A	\$1,800
	Rebuilt	\$1,200	\$1,200	\$1,200
	Overhaul	\$900	\$900	\$900
	<b>6 Cylinder Turbo</b>			
New	\$1,900	N/A	\$1,900	
Rebuilt	\$1,300	\$1,300	\$1,300	
Overhaul	\$1,000	\$1,000	\$1,000	

## New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-AEIO-320-D1B	\$17,560
NC-AEIO-320-D2B	\$17,560
NC-AEIO-320-E1B	\$17,560
NC-AEIO-320-E2B	\$17,560
NC-AEIO-360-A1A	\$18,860
NC-AEIO-360-A1B	\$18,860
NC-AEIO-360-A1B6	\$18,860
NC-AEIO-360-A1D	\$18,860
NC-AEIO-360-A1E	\$18,860
NC-AEIO-360-A2C	\$18,860
NC-AEIO-360-B1B	\$18,860
NC-AEIO-360-B1F	\$18,860
NC-AEIO-360-B1G6	\$18,860
NC-AEIO-360-B1H	\$18,860
NC-AEIO-360-B2F	\$18,860
NC-AEIO-360-B4A	\$18,860
NC-AEIO-360-H1A	\$18,860
NC-AEIO-360-H1B	\$18,860
NC-AEIO-540-D4A5	\$21,870
NC-AEIO-540-D4B5	\$21,870
NC-AEIO-540-D4D5	\$21,870
NC-AEIO-540-L1B5	\$24,170
NC-AEIO-540-L1B5D	\$24,170
NC-HIO-360-A1A	\$18,860
NC-HIO-360-B1A	\$18,860
NC-HIO-360-C1A	\$18,860
NC-HIO-360-C1B	\$18,860
NC-HIO-360-D1A	\$18,860
NC-HIO-360-E1AD	\$18,860
NC-HIO-360-E1BD	\$18,860
NC-HIO-360-F1AD	\$18,860
NC-HIO-360-G1A	\$18,860
NC-HO-360-C1A	\$17,560
NC-IO-320-B1A	\$17,560
NC-IO-320-D1A	\$17,560
NC-IO-320-D1B	\$17,560
NC-IO-320-E1B	\$17,560
NC-IO-320-E2A	\$17,560
NC-IO-320-E2B	\$17,560
NC-IO-360-A1A	\$18,560
NC-IO-360-A1B	\$18,560
NC-IO-360-A1B6	\$18,560
NC-IO-360-A1B6D	\$18,560
NC-IO-360-A1D	\$18,560
NC-IO-360-A1D6	\$18,560
NC-IO-360-A2B	\$18,560
NC-IO-360-A3B6	\$18,560
NC-IO-360-A3B6D	\$18,560

Select Exchange Engine Core	
Part Number	Value
SC-AEIO-320-D1B	\$15,100
SC-AEIO-320-D2B	\$15,100
SC-AEIO-320-E1B	\$15,100
SC-AEIO-320-E2B	\$15,100
SC-AEIO-360-A1A	\$16,400
SC-AEIO-360-A1B	\$16,400
SC-AEIO-360-A1B6	\$16,400
SC-AEIO-360-A1D	\$16,400
SC-AEIO-360-A1E	\$16,400
SC-AEIO-360-A2C	\$16,400
SC-AEIO-360-B1B	\$16,400
SC-AEIO-360-B1F	\$16,400
SC-AEIO-360-B1G6	\$16,400
SC-AEIO-360-B1H	\$16,400
SC-AEIO-360-B2F	\$16,400
SC-AEIO-360-B4A	\$16,400
SC-AEIO-360-H1A	\$16,400
SC-AEIO-360-H1B	\$16,400
SC-AEIO-540-D4A5	\$19,400
SC-AEIO-540-D4B5	\$19,400
SC-AEIO-540-D4D5	\$19,400
SC-AEIO-540-L1B5	\$21,700
SC-AEIO-540-L1B5D	\$21,700
SC-HIO-360-A1A	\$16,400
SC-HIO-360-B1A	\$16,400
SC-HIO-360-C1A	\$16,400
SC-HIO-360-C1B	\$16,400
SC-HIO-360-D1A	\$16,400
SC-HIO-360-E1AD	\$16,400
SC-HIO-360-E1BD	\$16,400
SC-HIO-360-F1AD	\$16,400
SC-HIO-360-G1A	\$16,400
SC-HO-360-C1A	\$15,100
SC-IO-320-B1A	\$15,100
SC-IO-320-D1A	\$15,100
SC-IO-320-D1B	\$15,100
SC-IO-320-E1B	\$15,100
SC-IO-320-E2A	\$15,100
SC-IO-320-E2B	\$15,100
SC-IO-360-A1A	\$16,100
SC-IO-360-A1B	\$16,100
SC-IO-360-A1B6	\$16,100
SC-IO-360-A1B6D	\$16,100
SC-IO-360-A1D	\$16,100
SC-IO-360-A1D6	\$16,100
SC-IO-360-A2B	\$16,100
SC-IO-360-A3B6	\$16,100
SC-IO-360-A3B6D	\$16,100

## New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-IO-360-B1B	\$18,560
NC-IO-360-B1E	\$18,560
NC-IO-360-B1F	\$18,560
NC-IO-360-B1G6	\$18,560
NC-IO-360-C1B	\$18,560
NC-IO-360-C1C	\$18,560
NC-IO-360-C1C6	\$18,560
NC-IO-360-C1D6	\$18,560
NC-IO-360-C1E6	\$18,560
NC-IO-360-C1F	\$18,560
NC-IO-360-C1G6	\$18,560
NC-IO-360-L2A	\$18,560
NC-IO-360-M1A	\$18,560
NC-IO-360-M1B	\$18,560
NC-IO-540-AA1A5	\$21,870
NC-IO-540-AA1B5	\$21,870
NC-IO-540-AB1A5	\$21,870
NC-IO-540-AC1A5	\$21,870
NC-IO-540-AE1A5	\$21,870
NC-IO-540-C1B5	\$21,870
NC-IO-540-C4B5	\$21,870
NC-IO-540-C4D5	\$21,870
NC-IO-540-C4D5D	\$21,870
NC-IO-540-D4A5	\$21,870
NC-IO-540-D4B5	\$21,870
NC-IO-540-G1D5	\$21,870
NC-IO-540-J4A5	\$21,870
NC-IO-540-K1A5	\$21,870
NC-IO-540-K1A5D	\$21,870
NC-IO-540-K1B5	\$21,870
NC-IO-540-K1D5	\$21,870
NC-IO-540-K1E5	\$21,870
NC-IO-540-K1F5	\$21,870
NC-IO-540-K1G5	\$21,870
NC-IO-540-K1G5D	\$21,870
NC-IO-540-K1J5	\$21,870
NC-IO-540-K1J5D	\$21,870
NC-IO-540-K1K5	\$21,870
NC-IO-540-L1C5	\$21,870
NC-IO-540-M1A5	\$21,870
NC-IO-540-M1B5D	\$21,870
NC-IO-540-M1C5	\$21,870
NC-IO-540-N1A5	\$21,870
NC-IO-540-R1A5	\$21,870
NC-IO-540-S1A5	\$21,870
NC-IO-540-T4A5D	\$21,870
NC-IO-540-T4B5	\$21,870
NC-IO-540-T4B5D	\$21,870

Select Exchange Engine Core	
Part Number	Value
SC-IO-360-B1B	\$16,100
SC-IO-360-B1E	\$16,100
SC-IO-360-B1F	\$16,100
SC-IO-360-B1G6	\$16,100
SC-IO-360-C1B	\$16,100
SC-IO-360-C1C	\$16,100
SC-IO-360-C1C6	\$16,100
SC-IO-360-C1D6	\$16,100
SC-IO-360-C1E6	\$16,100
SC-IO-360-C1F	\$16,100
SC-IO-360-C1G6	\$16,100
SC-IO-360-L2A	\$16,100
SC-IO-360-M1A	\$16,100
SC-IO-360-M1B	\$16,100
SC-IO-540-AA1A5	\$19,400
SC-IO-540-AA1B5	\$19,400
SC-IO-540-AB1A5	\$19,400
SC-IO-540-AC1A5	\$19,400
SC-IO-540-AE1A5	\$19,400
SC-IO-540-C1B5	\$19,400
SC-IO-540-C4B5	\$19,400
SC-IO-540-C4D5	\$19,400
SC-IO-540-C4D5D	\$19,400
SC-IO-540-D4A5	\$19,400
SC-IO-540-D4B5	\$19,400
SC-IO-540-G1D5	\$19,400
SC-IO-540-J4A5	\$19,400
SC-IO-540-K1A5	\$19,400
SC-IO-540-K1A5D	\$19,400
SC-IO-540-K1B5	\$19,400
SC-IO-540-K1D5	\$19,400
SC-IO-540-K1E5	\$19,400
SC-IO-540-K1F5	\$19,400
SC-IO-540-K1G5	\$19,400
SC-IO-540-K1G5D	\$19,400
SC-IO-540-K1J5	\$19,400
SC-IO-540-K1J5D	\$19,400
SC-IO-540-K1K5	\$19,400
SC-IO-540-L1C5	\$19,400
SC-IO-540-M1A5	\$19,400
SC-IO-540-M1B5D	\$19,400
SC-IO-540-M1C5	\$19,400
SC-IO-540-N1A5	\$19,400
SC-IO-540-R1A5	\$19,400
SC-IO-540-S1A5	\$19,400
SC-IO-540-T4A5D	\$19,400
SC-IO-540-T4B5	\$19,400
SC-IO-540-T4B5D	\$19,400

## New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-IO-540-V4A5	\$21,870
NC-IO-540-W1A5	\$21,870
NC-IO-540-W1A5D	\$21,870
NC-IO-720-A1B	\$49,450
NC-IO-720-B1B	\$49,450
NC-IO-720-D1B	\$49,450
NC-IO-720-D1C	\$49,450
NC-LIO-320-B1A	\$17,560
NC-LIO-360-C1E6	\$18,560
NC-LIO-360-M1A	\$18,560
NC-LO-360-A1G6D	\$17,560
NC-LO-360-A1H6	\$17,560
NC-LO-360-E1A6D	\$17,560
NC-LTIO-540-F2BD	\$28,100
NC-LTIO-540-J2B	\$28,100
NC-LTIO-540-J2B	\$28,100
NC-LTIO-540-J2BD	\$28,100
NC-LTIO-540-U2A	\$35,500
NC-LTO-360-E1A6D	\$22,490
NC-O-235-C1	\$15,950
NC-O-235-C1B	\$15,950
NC-O-235-C2A	\$15,950
NC-O-235-C2C	\$15,950
NC-O-235-F2B	\$15,950
NC-O-235-H2C	\$15,950
NC-O-235-J2A	\$15,950
NC-O-235-K2B	\$15,950
NC-O-235-K2C	\$15,950
NC-O-235-L2A	\$15,950
NC-O-235-L2C	\$15,950
NC-O-235-N2A	\$15,950
NC-O-235-N2C	\$15,950
NC-O-320-A2A	\$17,260
NC-O-320-A2B	\$17,260
NC-O-320-A2C	\$17,260
NC-O-320-A2D	\$17,260
NC-O-320-A3A	\$17,260
NC-O-320-A3B	\$17,260
NC-O-320-B1A	\$17,260
NC-O-320-B2A	\$17,260
NC-O-320-B2B	\$17,260
NC-O-320-B2B	\$17,260
NC-O-320-B2C	\$17,260
NC-O-320-B2D	\$17,260
NC-O-320-B3B	\$17,260
NC-O-320-D1A	\$17,260
NC-O-320-D1D	\$17,260
NC-O-320-D1F	\$17,260

Select Exchange Engine Core	
Part Number	Value
SC-IO-540-V4A5	\$19,400
SC-IO-540-W1A5	\$19,400
SC-IO-540-W1A5D	\$19,400
SC-IO-720-A1B	N/A
SC-IO-720-B1B	N/A
SC-IO-720-D1B	N/A
SC-IO-720-D1C	N/A
SC-LIO-320-B1A	\$15,100
SC-LIO-360-C1E6	\$16,100
SC-LIO-360-M1A	\$16,100
SC-LO-360-A1G6D	\$15,100
SC-LO-360-A1H6	\$15,100
SC-LO-360-E1A6D	\$15,100
SC-LTIO-540-F2BD	\$23,900
SC-LTIO-540-J2B	\$23,900
SC-LTIO-540-J2B	\$23,900
SC-LTIO-540-J2BD	\$23,900
SC-LTIO-540-U2A	\$31,300
SC-LTO-360-E1A6D	\$18,300
SC-O-235-C1	\$14,100
SC-O-235-C1B	\$14,100
SC-O-235-C2A	\$14,100
SC-O-235-C2C	\$14,100
SC-O-235-F2B	\$14,100
SC-O-235-H2C	\$14,100
SC-O-235-J2A	\$14,100
SC-O-235-K2B	\$14,100
SC-O-235-K2C	\$14,100
SC-O-235-L2A	\$14,100
SC-O-235-L2C	\$14,100
SC-O-235-N2A	\$14,100
SC-O-235-N2C	\$14,100
SC-O-320-A2A	\$14,800
SC-O-320-A2B	\$14,800
SC-O-320-A2C	\$14,800
SC-O-320-A2D	\$14,800
SC-O-320-A3A	\$14,800
SC-O-320-A3B	\$14,800
SC-O-320-B1A	\$14,800
SC-O-320-B2A	\$14,800
SC-O-320-B2B	\$14,800
SC-O-320-B2B	\$14,800
SC-O-320-B2C	\$14,800
SC-O-320-B2D	\$14,800
SC-O-320-B3B	\$14,800
SC-O-320-D1A	\$14,800
SC-O-320-D1D	\$14,800
SC-O-320-D1F	\$14,800

## New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-O-320-D2A	\$17,260
NC-O-320-D2B	\$17,260
NC-O-320-D2G	\$17,260
NC-O-320-D2J	\$17,260
NC-O-320-D3G	\$17,260
NC-O-320-D3G	\$17,260
NC-O-320-E2A	\$17,260
NC-O-320-E2C	\$17,260
NC-O-320-E2D	\$17,260
NC-O-320-E2F	\$17,260
NC-O-320-E2G	\$17,260
NC-O-320-E3D	\$17,260
NC-O-320-H2AD	\$17,260
NC-O-360-A1A	\$17,560
NC-O-360-A1AD	\$17,560
NC-O-360-A1D	\$17,560
NC-O-360-A1F6	\$17,560
NC-O-360-A1F6D	\$17,560
NC-O-360-A1G6D	\$17,560
NC-O-360-A1H6	\$17,560
NC-O-360-A1LD	\$17,560
NC-O-360-A1P	\$17,560
NC-O-360-A2A	\$17,560
NC-O-360-A2F	\$17,560
NC-O-360-A2G	\$17,560
NC-O-360-A3A	\$17,560
NC-O-360-A3AD	\$17,560
NC-O-360-A4A	\$17,560
NC-O-360-A4G	\$17,560
NC-O-360-A4J	\$17,560
NC-O-360-A4K	\$17,560
NC-O-360-A4M	\$17,560
NC-O-360-A4N	\$17,560
NC-O-360-A4P	\$17,560
NC-O-360-A5AD	\$17,560
NC-O-360-C1E	\$17,560
NC-O-360-C1F	\$17,560
NC-O-360-C1G	\$17,560
NC-O-360-C2A	\$17,560
NC-O-360-C2E	\$17,560
NC-O-360-C4F	\$17,560
NC-O-360-C4P	\$17,560
NC-O-360-E1A6D	\$17,560
NC-O-360-F1A6	\$17,560
NC-O-360-J2A	\$17,560
NC-O-540-A1A5	\$20,070
NC-O-540-A1B5	\$20,070
NC-O-540-A1C5	\$20,070

Select Exchange Engine Core	
Part Number	Value
SC-O-320-D2A	\$14,800
SC-O-320-D2B	\$14,800
SC-O-320-D2G	\$14,800
SC-O-320-D2J	\$14,800
SC-O-320-D3G	\$14,800
SC-O-320-D3G	\$14,800
SC-O-320-E2A	\$14,800
SC-O-320-E2C	\$14,800
SC-O-320-E2D	\$14,800
SC-O-320-E2F	\$14,800
SC-O-320-E2G	\$14,800
SC-O-320-E3D	\$14,800
SC-O-320-H2AD	\$14,800
SC-O-360-A1A	\$15,100
SC-O-360-A1AD	\$15,100
SC-O-360-A1D	\$15,100
SC-O-360-A1F6	\$15,100
SC-O-360-A1F6D	\$15,100
SC-O-360-A1G6D	\$15,100
SC-O-360-A1H6	\$15,100
SC-O-360-A1LD	\$15,100
SC-O-360-A1P	\$15,100
SC-O-360-A2A	\$15,100
SC-O-360-A2F	\$15,100
SC-O-360-A2G	\$15,100
SC-O-360-A3A	\$15,100
SC-O-360-A3AD	\$15,100
SC-O-360-A4A	\$15,100
SC-O-360-A4G	\$15,100
SC-O-360-A4J	\$15,100
SC-O-360-A4K	\$15,100
SC-O-360-A4M	\$15,100
SC-O-360-A4N	\$15,100
SC-O-360-A4P	\$15,100
SC-O-360-A5AD	\$15,100
SC-O-360-C1E	\$15,100
SC-O-360-C1F	\$15,100
SC-O-360-C1G	\$15,100
SC-O-360-C2A	\$15,100
SC-O-360-C2E	\$15,100
SC-O-360-C4F	\$15,100
SC-O-360-C4P	\$15,100
SC-O-360-E1A6D	\$15,100
SC-O-360-F1A6	\$15,100
SC-O-360-J2A	\$15,100
SC-O-540-A1A5	\$17,600
SC-O-540-A1B5	\$17,600
SC-O-540-A1C5	\$17,600

## New and Select Exchange Engine Core Value Tables

New Exchange Engine Core	
Part Number	Value
NC-O-540-A1D5	\$20,070
NC-O-540-A4D5	\$20,070
NC-O-540-B1A5	\$21,170
NC-O-540-B2B5	\$21,170
NC-O-540-B2C5	\$21,170
NC-O-540-B4B5	\$21,170
NC-O-540-E4A5	\$21,170
NC-O-540-E4B5	\$21,170
NC-O-540-E4C5	\$21,170
NC-O-540-F1B5	\$21,170
NC-O-540-G1A5	\$21,170
NC-O-540-H2A5	\$21,170
NC-O-540-J1A5D	\$21,170
NC-O-540-J3A5	\$21,170
NC-O-540-J3A5D	\$21,170
NC-O-540-J3C5D	\$21,170
NC-O-540-L3C5D	\$21,170
NC-TIO-360-C1A6D	\$22,490
NC-TIO-540-A2B	\$28,100
NC-TIO-540-A2C	\$28,100
NC-TIO-540-AA1AD	\$28,100
NC-TIO-540-AB1AD	\$28,100
NC-TIO-540-AB1BD	\$28,100
NC-TIO-540-AE2A	\$28,100
NC-TIO-540-AF1B	\$28,100
NC-TIO-540-AG1A	\$28,100
NC-TIO-540-AH1A	\$28,100
NC-TIO-540-AJ1A	\$28,100
NC-TIO-540-AK1A	\$28,100
NC-TIO-540-C1A	\$28,100
NC-TIO-540-F2BD	\$28,100
NC-TIO-540-J2B	\$28,100
NC-TIO-540-J2B	\$28,100
NC-TIO-540-J2BD	\$28,100
NC-TIO-540-S1AD	\$28,100
NC-TIO-540-U2A	\$35,500
NC-TIO-540-W2A	\$35,500
NC-TO-360-C1A6D	\$22,490
NC-TO-360-E1A6D	\$22,490

Select Exchange Engine Core	
Part Number	Value
SC-O-540-A1D5	\$17,600
SC-O-540-A4D5	\$17,600
SC-O-540-B1A5	\$18,700
SC-O-540-B2B5	\$18,700
SC-O-540-B2C5	\$18,700
SC-O-540-B4B5	\$18,700
SC-O-540-E4A5	\$18,700
SC-O-540-E4B5	\$18,700
SC-O-540-E4C5	\$18,700
SC-O-540-F1B5	\$18,700
SC-O-540-G1A5	\$18,700
SC-O-540-H2A5	\$18,700
SC-O-540-J1A5D	\$18,700
SC-O-540-J3A5	\$18,700
SC-O-540-J3A5D	\$18,700
SC-O-540-J3C5D	\$18,700
SC-O-540-L3C5D	\$18,700
SC-TIO-360-C1A6D	\$18,300
SC-TIO-540-A2B	\$23,900
SC-TIO-540-A2C	\$23,900
SC-TIO-540-AA1AD	\$23,900
SC-TIO-540-AB1AD	\$23,900
SC-TIO-540-AB1BD	\$23,900
SC-TIO-540-AE2A	\$23,900
SC-TIO-540-AF1B	\$23,900
SC-TIO-540-AG1A	\$23,900
SC-TIO-540-AH1A	\$23,900
SC-TIO-540-AJ1A	\$23,900
SC-TIO-540-AK1A	\$23,900
SC-TIO-540-C1A	\$23,900
SC-TIO-540-F2BD	\$23,900
SC-TIO-540-J2B	\$23,900
SC-TIO-540-J2B	\$23,900
SC-TIO-540-J2BD	\$23,900
SC-TIO-540-S1AD	\$23,900
SC-TIO-540-U2A	\$31,300
SC-TIO-540-W2A	\$31,300
SC-TO-360-C1A6D	\$18,300
SC-TO-360-E1A6D	\$18,300

LYCOMING AFTERMARKET ENGINE PRICE LIST  
Effective January 1, 2012  
(Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-235-C1	N/A	ENPL-9057	\$ 40,576	C	RENPL-9057	\$ 27,819	C	HENPL-9057	\$ 24,770	C	\$ 12,900
O-235-C1	N/A	ENPL-9080	\$ 40,332	C	RENPL-9080	\$ 27,196	C	HENPL-9080	\$ 24,147	C	\$ 12,900
O-235-C1	N/A	ENPL-9091	\$ 40,386	C	RENPL-9091	\$ 27,132	C	HENPL-9091	\$ 24,083	C	\$ 12,900
O-235-C1B	N/A	ENPL-9036	\$ 40,301	C	RENPL-9036	\$ 26,934	C	HENPL-9036	\$ 23,885	C	\$ 12,900
O-235-C1B	N/A	ENPL-9084	\$ 40,921	C	RENPL-9084	\$ 27,708	C	HENPL-9084	\$ 24,659	C	\$ 12,900
O-235-C2A	N/A	ENPL-9039	\$ 40,935	C	RENPL-9039	\$ 27,662	C	HENPL-9039	\$ 24,613	C	\$ 12,900
O-235-C2A	N/A	ENPL-9044	\$ 40,935	C	RENPL-9044	\$ 27,544	C	HENPL-9044	\$ 24,495	C	\$ 12,900
O-235-C2A	N/A	ENPL-9102	\$ 40,935	C	RENPL-9102	\$ 27,544	C	HENPL-9102	\$ 24,495	C	\$ 12,900
O-235-C2C	N/A	ENPL-9015	\$ 41,500	C	RENPL-9015	\$ 28,086	C	HENPL-9015	\$ 25,037	C	\$ 12,900
O-235-C2C	N/A	ENPL-9082	\$ 40,589	C	RENPL-9082	\$ 27,270	C	HENPL-9082	\$ 24,221	C	\$ 12,900
O-235-F2B	N/A	ENPL-9418	\$ 40,816	C	RENPL-9418	\$ 27,428	C	HENPL-9418	\$ 24,380	C	\$ 12,900
O-235-H2C	N/A	ENPL-6457	\$ 41,200	C	RENPL-6457	\$ 27,798	C	HENPL-6457	\$ 24,749	C	\$ 12,900
O-235-H2C	N/A	ENPL-9006	\$ 39,987	C	RENPL-9006	\$ 26,632	C	HENPL-9006	\$ 23,583	C	\$ 12,900
O-235-H2C	N/A	ENPL-9104	\$ 39,629	C	RENPL-9104	\$ 26,289	C	HENPL-9104	\$ 23,240	C	\$ 12,900
O-235-J2A	N/A	ENPL-9023	\$ 40,488	C	RENPL-9023	\$ 28,618	C	HENPL-9023	\$ 25,569	C	\$ 12,900
O-235-K2B	N/A	ENPL-9029	\$ 40,744	C	RENPL-9029	\$ 27,183	C	HENPL-9029	\$ 24,134	C	\$ 12,900
O-235-K2C	N/A	ENPL-6481	\$ 40,727	C	RENPL-6481	\$ 27,167	C	HENPL-6481	\$ 24,118	C	\$ 12,900
O-235-K2C	N/A	ENPL-9069	\$ 40,747	C	RENPL-9069	\$ 27,186	C	HENPL-9069	\$ 24,137	C	\$ 12,900
O-235-L2A	N/A	ENPL-6427	\$ 40,750	C	RENPL-6427	\$ 27,189	C	HENPL-6427	\$ 24,140	B	\$ 12,900
O-235-L2A	N/A	ENPL-9016	\$ 40,827	C	RENPL-9016	\$ 27,262	C	HENPL-9016	\$ 24,213	A	\$ 12,900
O-235-L2A	N/A	ENPL-9032	\$ 39,617	C	RENPL-9032	\$ 26,221	C	HENPL-9032	\$ 23,172	B	\$ 12,900
O-235-L2A	N/A	ENPL-9037	\$ 40,665	C	RENPL-9037	\$ 27,225	C	HENPL-9037	\$ 24,176	B	\$ 12,900
O-235-L2A	N/A	ENPL-9065	\$ 41,147	C	RENPL-9065	\$ 27,567	C	HENPL-9065	\$ 24,518	B	\$ 12,900
O-235-L2C	N/A	ENPL-6397	\$ 40,249	C	RENPL-6397	\$ 26,711	C	HENPL-6397	\$ 23,662	B	\$ 12,900
O-235-L2C	N/A	ENPL-6403	\$ 40,217	C	RENPL-6403	\$ 26,680	C	HENPL-6403	\$ 23,631	B	\$ 12,900
O-235-L2C	N/A	ENPL-6475	\$ 40,960	C	RENPL-6475	\$ 28,019	C	HENPL-6475	\$ 24,970	B	\$ 12,900
O-235-L2C	N/A	ENPL-6479	\$ 40,397	C	RENPL-6479	\$ 26,793	C	HENPL-6479	\$ 23,744	A	\$ 12,900
O-235-L2C	N/A	ENPL-9005	\$ 40,693	C	RENPL-9005	\$ 27,546	C	HENPL-9005	\$ 24,498	B	\$ 12,900
O-235-L2C	N/A	ENPL-9089	\$ 40,364	C	RENPL-9089	\$ 26,820	C	HENPL-9089	\$ 23,771	B	\$ 12,900
O-235-N2A	N/A	ENPL-9031	\$ 40,420	C	RENPL-9031	\$ 26,873	C	HENPL-9031	\$ 23,825	C	\$ 12,900
O-235-N2C	N/A	ENPL-6476	\$ 39,984	C	RENPL-6476	\$ 26,458	C	HENPL-6476	\$ 23,409	C	\$ 12,900
O-235-N2C	N/A	ENPL-9072	\$ 40,845	C	RENPL-9072	\$ 27,279	C	HENPL-9072	\$ 24,230	C	\$ 12,900
O-235-N2C	N/A	ENPL-9085	\$ 39,945	C	RENPL-9085	\$ 26,421	C	HENPL-9085	\$ 23,372	C	\$ 12,900
O-235-N2C	N/A	ENPL-9106	\$ 41,182	C	RENPL-9106	\$ 27,600	C	HENPL-9106	\$ 24,552	C	\$ 12,900
AEIO-320-D1B	YES	ENPL-RT8428	\$ 50,770	C	RENPL-RT8428	\$ 35,265	C	HENPL-RT8428	\$ 31,607	C	\$ 13,900
AEIO-320-D1B	YES	ENPL-RT9313	\$ 50,336	C	RENPL-RT9313	\$ 34,851	C	HENPL-RT9313	\$ 31,193	C	\$ 13,900
AEIO-320-D1B	YES	ENPL-RT9675	\$ 50,784	C	RENPL-RT9675	\$ 35,278	C	HENPL-RT9675	\$ 31,619	C	\$ 13,900
AEIO-320-D2B	YES	ENPL-RT9787	\$ 51,659	C	RENPL-RT9787	\$ 36,112	C	HENPL-RT9787	\$ 32,454	C	\$ 13,900
AEIO-320-E1B	YES	ENPL-RT8127	\$ 50,561	C	RENPL-RT8127	\$ 35,065	C	HENPL-RT8127	\$ 31,407	C	\$ 13,900
AEIO-320-E2B	YES	ENPL-RT8128	\$ 50,432	C	RENPL-RT8128	\$ 34,942	C	HENPL-RT8128	\$ 31,284	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT10053	\$ 47,529	C	RENPL-RT10053	\$ 32,174	C	HENPL-RT10053	\$ 28,515	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT8579	\$ 48,397	C	RENPL-RT8579	\$ 33,002	C	HENPL-RT8579	\$ 29,343	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT8710	\$ 47,809	C	RENPL-RT8710	\$ 32,441	C	HENPL-RT8710	\$ 28,782	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT9387	\$ 52,153	C	RENPL-RT9387	\$ 36,583	C	HENPL-RT9387	\$ 32,924	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT9525	\$ 47,956	C	RENPL-RT9525	\$ 32,581	C	HENPL-RT9525	\$ 28,923	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT9682	\$ 48,630	C	RENPL-RT9682	\$ 33,224	C	HENPL-RT9682	\$ 29,565	C	\$ 13,900
IO-320-B1A	YES	ENPL-RT9982	\$ 48,625	C	RENPL-RT9982	\$ 33,219	C	HENPL-RT9982	\$ 29,560	C	\$ 13,900
IO-320-D1A	YES	ENPL-RT9846	\$ 48,020	C	RENPL-RT9846	\$ 32,642	C	HENPL-RT9846	\$ 28,984	C	\$ 13,900
IO-320-D1B	YES	ENPL-RT10021	\$ 47,750	C	RENPL-RT10021	\$ 32,385	C	HENPL-RT10021	\$ 28,726	C	\$ 13,900
IO-320-D1B	YES	ENPL-RT8787	\$ 47,520	C	RENPL-RT8787	\$ 32,166	C	HENPL-RT8787	\$ 28,507	C	\$ 13,900
IO-320-D1B	YES	ENPL-RT8907	\$ 48,562	C	RENPL-RT8907	\$ 33,160	C	HENPL-RT8907	\$ 29,501	C	\$ 13,900
IO-320-E1B	YES	ENPL-RT9741	\$ 48,152	C	RENPL-RT9741	\$ 32,768	C	HENPL-RT9741	\$ 29,110	C	\$ 13,900
IO-320-E2A	YES	ENPL-RT8557	\$ 48,057	C	RENPL-RT8557	\$ 32,678	C	HENPL-RT8557	\$ 29,019	C	\$ 13,900
IO-320-E2B	YES	ENPL-RT8862	\$ 48,117	C	RENPL-RT8862	\$ 32,735	C	HENPL-RT8862	\$ 29,076	C	\$ 13,900
LIO-320-B1A	YES	ENPL-RT8889	\$ 49,344	C	RENPL-RT8889	\$ 33,905	C	HENPL-RT8889	\$ 30,246	C	\$ 13,900

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
<b>ENGINE MODEL</b>	<b>ROLLER TAPPETS</b>	<b>NEW</b>			<b>REBUILT ("ZERO" TIME)</b>			<b>OVERHAUL</b>			
		<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>CORE VALUE</b>
LIO-320-B1A	YES	ENPL-RT9638	\$ 48,840	C	RENPL-RT9638	\$ 33,424	C	HENPL-RT9638	\$ 29,766	C	\$ 13,900
LIO-320-B1A	YES	ENPL-RT9688	\$ 48,751	C	RENPL-RT9688	\$ 33,339	C	HENPL-RT9688	\$ 29,681	C	\$ 13,900
O-320-A2A	YES	ENPL-RT8989	\$ 44,233	C	RENPL-RT8989	\$ 29,452	C	HENPL-RT8989	\$ 25,793	C	\$ 13,600
O-320-A2B	YES	ENPL-RT10055	\$ 44,064	C	RENPL-RT10055	\$ 29,291	C	HENPL-RT10055	\$ 25,632	C	\$ 13,600
O-320-A2B	YES	ENPL-RT8553	\$ 42,964	C	RENPL-RT8553	\$ 28,336	C	HENPL-RT8553	\$ 24,678	C	\$ 13,600
O-320-A2B	YES	ENPL-RT8624	\$ 44,080	C	RENPL-RT8624	\$ 29,306	C	HENPL-RT8624	\$ 25,647	C	\$ 13,600
O-320-A2B	YES	ENPL-RT9379	\$ 44,252	C	RENPL-RT9379	\$ 29,469	C	HENPL-RT9379	\$ 25,811	C	\$ 13,600
O-320-A2B	YES	ENPL-RT9802	\$ 43,561	C	RENPL-RT9802	\$ 28,811	C	HENPL-RT9802	\$ 25,153	C	\$ 13,600
O-320-A2C	YES	ENPL-RT8821	\$ 44,368	C	RENPL-RT8821	\$ 29,581	C	HENPL-RT8821	\$ 25,922	C	\$ 13,600
O-320-A2D	YES	ENPL-RT8822	\$ 43,836	C	RENPL-RT8822	\$ 29,073	C	HENPL-RT8822	\$ 25,415	C	\$ 13,600
O-320-A3A	YES	ENPL-RT9393	\$ 44,514	C	RENPL-RT9393	\$ 29,720	C	HENPL-RT9393	\$ 26,061	C	\$ 13,600
O-320-A3B	YES	ENPL-RT9384	\$ 42,681	C	RENPL-RT9384	\$ 27,972	C	HENPL-RT9384	\$ 24,314	C	\$ 13,600
O-320-B1A	YES	ENPL-RT9467	\$ 44,230	C	RENPL-RT9467	\$ 29,449	C	HENPL-RT9467	\$ 25,790	C	\$ 13,600
O-320-B2A	YES	ENPL-RT9812	\$ 43,828	C	RENPL-RT9812	\$ 29,066	C	HENPL-RT9812	\$ 25,407	C	\$ 13,600
O-320-B2B	YES	ENPL-RT10067	\$ 43,153	C	RENPL-RT10067	\$ 28,422	C	HENPL-RT10067	\$ 24,763	C	\$ 13,600
O-320-B2B	YES	ENPL-RT8493	\$ 43,575	C	RENPL-RT8493	\$ 29,041	C	HENPL-RT8493	\$ 25,383	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9346	\$ 44,197	C	RENPL-RT9346	\$ 29,417	C	HENPL-RT9346	\$ 25,759	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9514	\$ 43,506	C	RENPL-RT9514	\$ 28,975	C	HENPL-RT9514	\$ 25,316	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9645	\$ 43,726	C	RENPL-RT9645	\$ 28,968	C	HENPL-RT9645	\$ 25,310	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9757	\$ 43,846	C	RENPL-RT9757	\$ 29,083	C	HENPL-RT9757	\$ 25,424	C	\$ 13,600
O-320-B2B	YES	ENPL-RT9892	\$ 43,626	C	RENPL-RT9892	\$ 28,970	C	HENPL-RT9892	\$ 25,312	C	\$ 13,600
O-320-B2B**	YES	ENPL-RT10428	\$ 44,303	C	RENPL-RT10428	\$ 29,518	C	HENPL-RT10428	\$ 25,859	C	\$ 13,600
O-320-B2C	YES	ENPL-RT8864	\$ 44,047	C	RENPL-RT8864	\$ 29,496	C	HENPL-RT8864	\$ 25,837	C	\$ 13,600
O-320-B2C	YES	ENPL-RT8940	\$ 44,422	C	RENPL-RT8940	\$ 29,607	C	HENPL-RT8940	\$ 25,948	C	\$ 13,600
O-320-B2C	YES	ENPL-RT9752	\$ 44,422	C	RENPL-RT9752	\$ 30,106	C	HENPL-RT9752	\$ 26,447	C	\$ 13,600
O-320-B2D	YES	ENPL-RT9487	\$ 43,337	C	RENPL-RT9487	\$ 28,597	C	HENPL-RT9487	\$ 24,939	C	\$ 13,600
O-320-B3B	YES	ENPL-RT10135	\$ 43,247	C	RENPL-RT10135	\$ 28,512	C	HENPL-RT10135	\$ 24,853	C	\$ 13,600
O-320-B3B	YES	ENPL-RT8587	\$ 43,771	C	RENPL-RT8587	\$ 29,011	C	HENPL-RT8587	\$ 25,353	C	\$ 13,600
O-320-B3B	YES	ENPL-RT9350	\$ 43,141	C	RENPL-RT9350	\$ 28,411	C	HENPL-RT9350	\$ 24,752	C	\$ 13,600
O-320-B3B	YES	ENPL-RT9850	\$ 43,925	C	RENPL-RT9850	\$ 29,158	C	HENPL-RT9850	\$ 25,499	C	\$ 13,600
O-320-B3B	YES	ENPL-RT9870	\$ 43,997	C	RENPL-RT9870	\$ 29,226	C	HENPL-RT9870	\$ 25,568	C	\$ 13,600
O-320-D1A	YES	ENPL-RT8508	\$ 43,348	C	RENPL-RT8508	\$ 29,035	C	HENPL-RT8508	\$ 25,376	C	\$ 13,600
O-320-D1A	YES	ENPL-RT8609	\$ 44,400	C	RENPL-RT8609	\$ 29,611	C	HENPL-RT8609	\$ 25,952	C	\$ 13,600
O-320-D1A	YES	ENPL-RT8760	\$ 43,844	C	RENPL-RT8760	\$ 29,081	C	HENPL-RT8760	\$ 25,422	C	\$ 13,600
O-320-D1A	YES	ENPL-RT8978	\$ 43,891	C	RENPL-RT8978	\$ 29,125	C	HENPL-RT8978	\$ 25,466	C	\$ 13,600
O-320-D1A	YES	ENPL-RT9314	\$ 44,113	C	RENPL-RT9314	\$ 29,337	C	HENPL-RT9314	\$ 25,679	C	\$ 13,600
O-320-D1A	YES	ENPL-RT9650	\$ 44,697	C	RENPL-RT9650	\$ 29,894	C	HENPL-RT9650	\$ 26,236	C	\$ 13,600
O-320-D1D	YES	ENPL-RT8144	\$ 44,198	C	RENPL-RT8144	\$ 29,419	C	HENPL-RT8144	\$ 25,760	C	\$ 13,600
O-320-D1D	YES	ENPL-RT9776	\$ 44,351	C	RENPL-RT9776	\$ 29,564	C	HENPL-RT9776	\$ 25,906	C	\$ 13,600
O-320-D1F	YES	ENPL-RT8556	\$ 44,350	C	RENPL-RT8556	\$ 29,563	C	HENPL-RT8556	\$ 25,904	C	\$ 13,600
O-320-D1F	YES	ENPL-RT9454	\$ 44,430	C	RENPL-RT9454	\$ 29,640	C	HENPL-RT9454	\$ 25,981	C	\$ 13,600
O-320-D2A	YES	ENPL-RT10006	\$ 44,209	C	RENPL-RT10006	\$ 29,429	C	HENPL-RT10006	\$ 25,770	C	\$ 13,600
O-320-D2A	YES	ENPL-RT10354	\$ 44,107	C	RENPL-RT10354	\$ 29,332	C	HENPL-RT10354	\$ 25,673	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8421	\$ 43,143	C	RENPL-RT8421	\$ 29,289	C	HENPL-RT8421	\$ 25,630	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8438	\$ 44,173	C	RENPL-RT8438	\$ 29,395	C	HENPL-RT8438	\$ 25,736	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8551	\$ 44,220	C	RENPL-RT8551	\$ 29,628	C	HENPL-RT8551	\$ 25,969	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8562	\$ 44,133	C	RENPL-RT8562	\$ 29,357	C	HENPL-RT8562	\$ 25,698	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8589	\$ 43,593	C	RENPL-RT8589	\$ 28,842	C	HENPL-RT8589	\$ 25,183	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8596	\$ 44,225	C	RENPL-RT8596	\$ 29,444	C	HENPL-RT8596	\$ 25,785	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8610	\$ 44,213	C	RENPL-RT8610	\$ 29,433	C	HENPL-RT8610	\$ 25,774	C	\$ 13,600
O-320-D2A	YES	ENPL-RT8748	\$ 44,151	C	RENPL-RT8748	\$ 29,373	C	HENPL-RT8748	\$ 25,715	C	\$ 13,600
O-320-D2A	YES	ENPL-RT9676	\$ 43,747	C	RENPL-RT9676	\$ 28,988	C	HENPL-RT9676	\$ 25,330	C	\$ 13,600
O-320-D2A	YES	ENPL-RT9767	\$ 43,699	C	RENPL-RT9767	\$ 28,943	C	HENPL-RT9767	\$ 25,284	C	\$ 13,600
O-320-D2A	YES	ENPL-RT9923	\$ 44,625	C	RENPL-RT9923	\$ 29,825	C	HENPL-RT9923	\$ 26,166	C	\$ 13,600
O-320-D2A	YES	ENPL-RT10359	\$ 43,391	C	RENPL-RT10359	\$ 28,649	C	HENPL-RT10359	\$ 24,990	C	\$ 13,600

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
<b>ENGINE MODEL</b>	<b>ROLLER TAPPETS</b>	<b>NEW</b>			<b>REBUILT ("ZERO" TIME)</b>			<b>OVERHAUL</b>			<b>CORE VALUE</b>
		<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	
O-320-D2B	YES	ENPL-RT8625	\$ 43,630	C	RENPL-RT8625	\$ 28,877	C	HENPL-RT8625	\$ 25,218	C	\$ 13,600
O-320-D2G	YES	ENPL-RT10156	\$ 43,060	C	RENPL-RT10156	\$ 28,333	C	HENPL-RT10156	\$ 24,674	C	\$ 13,600
O-320-D2G	YES	ENPL-RT10182	\$ 43,491	C	RENPL-RT10182	\$ 28,744	C	HENPL-RT10182	\$ 25,086	C	\$ 13,600
O-320-D2G	YES	ENPL-RT8024	\$ 43,431	C	RENPL-RT8024	\$ 28,687	C	HENPL-RT8024	\$ 25,029	C	\$ 13,600
O-320-D2G	YES	ENPL-RT8372	\$ 43,441	C	RENPL-RT8372	\$ 28,696	C	HENPL-RT8372	\$ 25,037	C	\$ 13,600
O-320-D2G	YES	ENPL-RT10240	\$ 43,030	C	RENPL-RT10240	\$ 28,245	C	HENPL-RT10240	\$ 24,586	C	\$ 13,600
O-320-D2J	YES	ENPL-RT8164	\$ 43,010	C	RENPL-RT8164	\$ 28,285	C	HENPL-RT8164	\$ 24,627	A	\$ 13,600
O-320-D2J	YES	ENPL-RT8373	\$ 42,990	C	RENPL-RT8373	\$ 28,479	C	HENPL-RT8373	\$ 24,821	B	\$ 13,600
O-320-D2J	YES	ENPL-RT9864	\$ 43,614	C	RENPL-RT9864	\$ 28,862	C	HENPL-RT9864	\$ 25,203	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10180	\$ 43,705	C	RENPL-RT10180	\$ 28,996	C	HENPL-RT10180	\$ 25,338	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10316	\$ 45,381	C	RENPL-RT10316	\$ 30,546	C	HENPL-RT10316	\$ 26,888	B	\$ 13,600
O-320-D3G	YES	ENPL-RT8150	\$ 43,075	C	RENPL-RT8150	\$ 28,347	C	HENPL-RT8150	\$ 24,689	A	\$ 13,600
O-320-D3G	YES	ENPL-RT8446	\$ 43,556	C	RENPL-RT8446	\$ 28,806	C	HENPL-RT8446	\$ 25,147	B	\$ 13,600
O-320-D3G	YES	ENPL-RT8585	\$ 43,569	C	RENPL-RT8585	\$ 28,818	C	HENPL-RT8585	\$ 25,159	B	\$ 13,600
O-320-D3G	YES	ENPL-RT8885	\$ 42,996	C	RENPL-RT8885	\$ 28,272	C	HENPL-RT8885	\$ 24,613	B	\$ 13,600
O-320-D3G	YES	ENPL-RT9649	\$ 44,826	C	RENPL-RT9649	\$ 29,824	C	HENPL-RT9649	\$ 26,166	B	\$ 13,600
O-320-D3G	YES	ENPL-RT9792	\$ 44,161	C	RENPL-RT9792	\$ 29,320	C	HENPL-RT9792	\$ 25,662	B	\$ 13,600
O-320-D3G	YES	ENPL-RT9910	\$ 44,118	C	RENPL-RT9910	\$ 29,342	C	HENPL-RT9910	\$ 25,683	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10300	\$ 43,968	C	RENPL-RT10300	\$ 29,199	C	HENPL-RT10300	\$ 25,540	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10445	\$ 43,620	C	RENPL-RT10445	\$ 28,866	C	HENPL-RT10445	\$ 25,207	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10447	\$ 42,106	C	RENPL-RT10447	\$ 28,542	C	HENPL-RT10447	\$ 24,884	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10477	\$ 43,684	C	RENPL-RT10477	\$ 28,907	C	HENPL-RT10477	\$ 25,249	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10665	\$ 48,869	C	RENPL-RT10665	\$ 32,612	C	HENPL-RT10665	\$ 28,953	B	\$ 13,600
O-320-D3G	YES	ENPL-RT10701	\$ 44,574	C	RENPL-RT10701	\$ 29,776	C	HENPL-RT10701	\$ 26,118	B	\$ 13,600
O-320-E2A	YES	ENPL-RT8590	\$ 43,642	C	RENPL-RT8590	\$ 28,888	C	HENPL-RT8590	\$ 25,230	C	\$ 13,600
O-320-E2A	YES	ENPL-RT8611	\$ 44,283	C	RENPL-RT8611	\$ 29,500	C	HENPL-RT8611	\$ 25,841	C	\$ 13,600
O-320-E2A	YES	ENPL-RT8626	\$ 44,577	C	RENPL-RT8626	\$ 29,779	C	HENPL-RT8626	\$ 26,121	C	\$ 13,600
O-320-E2A	YES	ENPL-RT8903	\$ 43,642	C	RENPL-RT8903	\$ 28,888	C	HENPL-RT8903	\$ 25,230	C	\$ 13,600
O-320-E2A	YES	ENPL-RT8923	\$ 44,283	C	RENPL-RT8923	\$ 29,500	C	HENPL-RT8923	\$ 25,841	C	\$ 13,600
O-320-E2A	YES	ENPL-RT9321	\$ 44,236	C	RENPL-RT9321	\$ 29,454	C	HENPL-RT9321	\$ 25,796	C	\$ 13,600
O-320-E2A	YES	ENPL-RT9744	\$ 43,791	C	RENPL-RT9744	\$ 29,030	C	HENPL-RT9744	\$ 25,372	C	\$ 13,600
O-320-E2C	YES	ENPL-RT10164	\$ 44,238	C	RENPL-RT10164	\$ 29,457	C	HENPL-RT10164	\$ 25,798	C	\$ 13,600
O-320-E2C	YES	ENPL-RT8564	\$ 44,574	C	RENPL-RT8564	\$ 29,777	C	HENPL-RT8564	\$ 26,118	C	\$ 13,600
O-320-E2D	YES	ENPL-RT10495	\$ 43,777	C	RENPL-RT10495	\$ 28,749	C	HENPL-RT10495	\$ 25,090	B	\$ 13,600
O-320-E2D	YES	ENPL-RT8031	\$ 43,437	C	RENPL-RT8031	\$ 28,740	C	HENPL-RT8031	\$ 25,082	B	\$ 13,600
O-320-E2D	YES	ENPL-RT8181	\$ 42,782	C	RENPL-RT8181	\$ 28,103	C	HENPL-RT8181	\$ 24,444	A	\$ 13,600
O-320-E2D	YES	ENPL-RT8797	\$ 43,905	C	RENPL-RT8797	\$ 29,139	C	HENPL-RT8797	\$ 25,480	B	\$ 13,600
O-320-E2D	YES	ENPL-RT8888	\$ 43,368	C	RENPL-RT8888	\$ 28,626	C	HENPL-RT8888	\$ 24,968	B	\$ 13,600
O-320-E2D	YES	ENPL-RT9695	\$ 44,058	C	RENPL-RT9695	\$ 29,284	C	HENPL-RT9695	\$ 25,626	B	\$ 13,600
O-320-E2D	YES	ENPL-RT9820	\$ 43,522	C	RENPL-RT9820	\$ 28,773	C	HENPL-RT9820	\$ 25,115	B	\$ 13,600
O-320-E2D	YES	ENPL-RT9947	\$ 43,437	C	RENPL-RT9947	\$ 28,692	C	HENPL-RT9947	\$ 25,034	B	\$ 13,600
O-320-E2D	YES	ENPL-RT10213	\$ 42,984	C	RENPL-RT10213	\$ 28,261	C	HENPL-RT10213	\$ 24,602	B	\$ 13,600
O-320-E2F	YES	ENPL-RT9619	\$ 43,685	C	RENPL-RT9619	\$ 28,929	C	HENPL-RT9619	\$ 25,270	C	\$ 13,600
O-320-E2G	YES	ENPL-RT8092	\$ 42,950	C	RENPL-RT8092	\$ 28,677	C	HENPL-RT8092	\$ 25,018	C	\$ 13,600
O-320-E2G	YES	ENPL-RT9738	\$ 43,597	C	RENPL-RT9738	\$ 28,845	C	HENPL-RT9738	\$ 25,186	C	\$ 13,600
O-320-E3D	YES	ENPL-RT8032	\$ 43,328	C	RENPL-RT8032	\$ 28,589	C	HENPL-RT8032	\$ 24,930	C	\$ 13,600
O-320-E3D	YES	ENPL-RT8310	\$ 42,909	C	RENPL-RT8310	\$ 28,401	C	HENPL-RT8310	\$ 24,742	C	\$ 13,600
O-320-E3D	YES	ENPL-RT9546	\$ 43,057	C	RENPL-RT9546	\$ 28,331	C	HENPL-RT9546	\$ 24,672	C	\$ 13,600
O-320-E3D	YES	ENPL-RT9665	\$ 43,273	C	RENPL-RT9665	\$ 28,536	C	HENPL-RT9665	\$ 24,877	C	\$ 13,600
O-320-E3D	YES	ENPL-RT9773	\$ 43,431	C	RENPL-RT9773	\$ 28,686	C	HENPL-RT9773	\$ 25,028	C	\$ 13,600
O-320-H2AD	N/A	ENPL-7259	\$ 46,613	C	RENPL-7259	\$ 31,721	C	HENPL-7259	\$ 28,063	B	\$ 13,600
O-320-H2AD	N/A	ENPL-7396	\$ 45,694	C	RENPL-7396	\$ 30,845	C	HENPL-7396	\$ 27,186	A	\$ 13,600
O-320-H2AD	N/A	ENPL-9837	\$ 45,903	C	RENPL-9837	\$ 31,044	C	HENPL-9837	\$ 27,385	B	\$ 13,600
O-320-H2AD	N/A	ENPL-9852	\$ 46,123	C	RENPL-9852	\$ 31,254	C	HENPL-9852	\$ 27,596	B	\$ 13,600
O-320-D1A	YES	ENPL-RT10659	\$ 43,913	C	RENPL-RT10659	\$ 29,147	C	HENPL-RT10659	\$ 25,488	C	\$ 13,600

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
<b>ENGINE MODEL</b>	<b>ROLLER TAPPETS</b>	<b>NEW</b>			<b>REBUILT ("ZERO" TIME)</b>			<b>OVERHAUL</b>			
		<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>CORE VALUE</b>
AEIO-360-A1A	YES	ENPL-RT8117	\$ 56,079	C	RENPL-RT8117	\$ 38,437	C	HENPL-RT8117	\$ 34,778	C	\$ 15,200
AEIO-360-A1B	YES	ENPL-RT8510	\$ 56,174	C	RENPL-RT8510	\$ 38,527	C	HENPL-RT8510	\$ 34,868	C	\$ 15,200
AEIO-360-A1B6	YES	ENPL-RT8524	\$ 56,890	C	RENPL-RT8524	\$ 39,210	C	HENPL-RT8524	\$ 35,551	C	\$ 15,200
AEIO-360-A1B6	YES	ENPL-RT8592	\$ 57,257	C	RENPL-RT8592	\$ 39,560	C	HENPL-RT8592	\$ 35,902	C	\$ 15,200
AEIO-360-A1B6	YES	ENPL-RT9363	\$ 56,933	C	RENPL-RT9363	\$ 39,251	C	HENPL-RT9363	\$ 35,592	C	\$ 15,200
AEIO-360-A1D	YES	ENPL-RT8665	\$ 55,159	C	RENPL-RT8665	\$ 37,560	C	HENPL-RT8665	\$ 33,901	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT8516	\$ 56,045	C	RENPL-RT8516	\$ 38,404	C	HENPL-RT8516	\$ 34,746	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT8526	\$ 55,158	C	RENPL-RT8526	\$ 37,559	C	HENPL-RT8526	\$ 33,900	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT9370	\$ 56,312	C	RENPL-RT9370	\$ 38,658	C	HENPL-RT9370	\$ 35,000	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT9533	\$ 56,045	C	RENPL-RT9533	\$ 38,404	C	HENPL-RT9533	\$ 34,746	C	\$ 15,200
AEIO-360-A1E	YES	ENPL-RT9719	\$ 55,684	C	RENPL-RT9719	\$ 38,060	C	HENPL-RT9719	\$ 34,401	C	\$ 15,200
AEIO-360-A2C	YES	ENPL-RT9462	\$ 62,380	C	RENPL-RT9462	\$ 44,444	C	HENPL-RT9462	\$ 40,786	C	\$ 15,200
AEIO-360-B1B	YES	ENPL-RT8300	\$ 55,700	C	RENPL-RT8300	\$ 38,075	C	HENPL-RT8300	\$ 34,417	C	\$ 15,200
AEIO-360-B1F	YES	ENPL-RT10555	\$ 58,439	C	RENPL-RT10555	\$ 41,007	C	HENPL-RT10555	\$ 37,348	C	\$ 15,200
AEIO-360-B1F	YES	ENPL-RT7304	\$ 55,346	C	RENPL-RT7304	\$ 38,032	C	HENPL-RT7304	\$ 34,373	C	\$ 15,200
AEIO-360-B1F	YES	ENPL-RT8432	\$ 55,368	C	RENPL-RT8432	\$ 38,054	C	HENPL-RT8432	\$ 34,395	C	\$ 15,200
AEIO-360-B1F	YES	ENPL-RT9771	\$ 57,143	C	RENPL-RT9771	\$ 39,761	C	HENPL-RT9771	\$ 36,102	C	\$ 15,200
AEIO-360-B1G6	YES	ENPL-RT8445	\$ 55,999	C	RENPL-RT8445	\$ 38,360	C	HENPL-RT8445	\$ 34,702	C	\$ 15,200
AEIO-360-B1H	YES	ENPL-RT9574	\$ 55,582	C	RENPL-RT9574	\$ 37,962	C	HENPL-RT9574	\$ 34,304	C	\$ 15,200
AEIO-360-B1H	YES	ENPL-RT9575	\$ 55,978	C	RENPL-RT9575	\$ 38,340	C	HENPL-RT9575	\$ 34,681	C	\$ 15,200
AEIO-360-B2F	YES	ENPL-RT8661	\$ 54,208	C	RENPL-RT8661	\$ 36,653	C	HENPL-RT8661	\$ 32,994	C	\$ 15,200
AEIO-360-B2F	YES	ENPL-RT8769	\$ 53,244	C	RENPL-RT8769	\$ 35,733	C	HENPL-RT8769	\$ 32,075	C	\$ 15,200
AEIO-360-B4A	YES	ENPL-RT8844	\$ 55,110	C	RENPL-RT8844	\$ 37,512	C	HENPL-RT8844	\$ 33,854	C	\$ 15,200
AEIO-360-H1A	YES	ENPL-RT8633	\$ 54,897	C	RENPL-RT8633	\$ 37,309	C	HENPL-RT8633	\$ 33,651	C	\$ 15,200
AEIO-360-H1A	YES	ENPL-RT9765	\$ 55,071	C	RENPL-RT9765	\$ 37,476	C	HENPL-RT9765	\$ 33,817	C	\$ 15,200
AEIO-360-H1A	YES	ENPL-RT9984	\$ 54,464	C	RENPL-RT9984	\$ 36,896	C	HENPL-RT9984	\$ 33,238	C	\$ 15,200
AEIO-360-H1B	YES	ENPL-RT10057	\$ 55,978	C	RENPL-RT10057	\$ 38,340	C	HENPL-RT10057	\$ 34,681	C	\$ 15,200
HIO-360-A1A	YES	ENPL-RT6879	\$ 64,964	C	RENPL-RT6879	\$ 46,908	C	HENPL-RT6879	\$ 43,250	C	\$ 15,200
HIO-360-B1A	YES	ENPL-RT9443	\$ 61,275	C	RENPL-RT9443	\$ 43,391	C	HENPL-RT9443	\$ 39,733	C	\$ 15,200
HIO-360-B1A	YES	ENPL-RT9874	\$ 61,234	C	RENPL-RT9874	\$ 43,352	C	HENPL-RT9874	\$ 39,693	C	\$ 15,200
HIO-360-C1A	N/A	ENPL-9985	\$ 60,631	C	RENPL-9985	\$ 42,777	C	HENPL-9985	\$ 39,118	C	\$ 15,200
HIO-360-C1A	N/A	ENPL-RT7287	\$ 61,851	C	RENPL-RT7287	\$ 43,940	C	HENPL-RT7287	\$ 40,282	C	\$ 15,200
HIO-360-C1B	YES	ENPL-RT9891	\$ 59,538	C	RENPL-RT9891	\$ 41,735	C	HENPL-RT9891	\$ 38,076	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-10007	\$ 57,855	C	RENPL-10007	\$ 40,397	C	HENPL-10007	\$ 36,739	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-10161	\$ 57,455	C	RENPL-10161	\$ 39,749	C	HENPL-10161	\$ 36,090	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-10208	\$ 57,475	C	RENPL-10208	\$ 39,768	C	HENPL-10208	\$ 36,109	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-10253	\$ 57,610	C	RENPL-10253	\$ 39,897	C	HENPL-10253	\$ 36,238	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-7486	\$ 57,585	C	RENPL-7486	\$ 39,873	C	HENPL-7486	\$ 36,214	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-7497	\$ 57,538	C	RENPL-7497	\$ 39,828	C	HENPL-7497	\$ 36,170	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-8996	\$ 58,331	C	RENPL-8996	\$ 40,855	C	HENPL-8996	\$ 37,196	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-9372	\$ 57,909	C	RENPL-9372	\$ 40,182	C	HENPL-9372	\$ 36,523	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-9431	\$ 57,650	C	RENPL-9431	\$ 39,934	C	HENPL-9431	\$ 36,275	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-9867	\$ 57,221	C	RENPL-9867	\$ 39,525	C	HENPL-9867	\$ 35,867	C	\$ 15,200
HIO-360-D1A	N/A	ENPL-9945	\$ 57,496	C	RENPL-9945	\$ 39,787	C	HENPL-9945	\$ 36,129	C	\$ 15,200
HIO-360-D1A ***	N/A	ENPL-9477	\$ 59,020	C	RENPL-9477	\$ 41,241	C	HENPL-9477	\$ 37,582	C	\$ 15,200
HIO-360-E1AD	N/A	ENPL-6819	\$ 60,451	D	RENPL-6819	\$ 42,605	D	HENPL-6819	\$ 38,947	D	\$ 15,200
HIO-360-E1AD	N/A	ENPL-9630	\$ 60,568	D	RENPL-9630	\$ 42,717	D	HENPL-9630	\$ 39,058	D	\$ 15,200
HIO-360-E1BD	N/A	ENPL-7022	\$ 60,263	D	RENPL-7022	\$ 42,426	D	HENPL-7022	\$ 38,768	D	\$ 15,200
HIO-360-E1BD	N/A	ENPL-9769	\$ 60,544	D	RENPL-9769	\$ 42,694	D	HENPL-9769	\$ 39,036	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-10041	\$ 59,875	D	RENPL-10041	\$ 42,056	D	HENPL-10041	\$ 38,397	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-10141	\$ 60,556	D	RENPL-10141	\$ 42,705	D	HENPL-10141	\$ 39,047	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-10557	\$ 60,894	D	RENPL-10557	\$ 43,028	D	HENPL-10557	\$ 39,369	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-8689	\$ 60,944	D	RENPL-8689	\$ 43,795	D	HENPL-8689	\$ 40,136	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-9818	\$ 60,889	D	RENPL-9818	\$ 43,023	D	HENPL-9818	\$ 39,365	D	\$ 15,200
HIO-360-F1AD	N/A	ENPL-9902	\$ 61,254	D	RENPL-9902	\$ 43,371	D	HENPL-9902	\$ 39,713	D	\$ 15,200

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
<b>ENGINE MODEL</b>	<b>ROLLER TAPPETS</b>	<b>NEW</b>			<b>REBUILT ("ZERO" TIME)</b>			<b>OVERHAUL</b>			<b>CORE VALUE</b>
		<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	
HIO-360-G1A	YES	ENPL-RT10152	\$ 50,224	C	RENPL-RT10152	\$ 32,854	C	HENPL-RT10152	\$ 29,195	C	\$ 15,200
HO-360-C1A	YES	ENPL-RT9396	\$ 50,092	C	RENPL-RT9396	\$ 34,618	C	HENPL-RT9396	\$ 30,960	C	\$ 13,900
HO-360-C1A	YES	ENPL-RT9707	\$ 50,092	C	RENPL-RT9707	\$ 34,618	C	HENPL-RT9707	\$ 30,960	C	\$ 13,900
HO-360-C1A	YES	ENPL-RT9881	\$ 49,820	C	RENPL-RT9881	\$ 34,359	C	HENPL-RT9881	\$ 30,700	C	\$ 13,900
HO-360-C1A	YES	ENPL-RT9946	\$ 49,991	C	RENPL-RT9946	\$ 34,521	C	HENPL-RT9946	\$ 30,863	C	\$ 13,900
IO-360-A1A	YES	ENPL-RT0441	\$ 55,198	C	RENPL-RT10441	\$ 38,016	C	HENPL-RT10441	\$ 34,358	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT8591	\$ 52,094	C	RENPL-RT8591	\$ 35,057	C	HENPL-RT8591	\$ 31,399	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT8668	\$ 51,847	C	RENPL-RT8668	\$ 34,821	C	HENPL-RT8668	\$ 31,163	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT8990	\$ 52,127	C	RENPL-RT8990	\$ 34,704	C	HENPL-RT8990	\$ 31,045	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT9635	\$ 52,258	C	RENPL-RT9635	\$ 35,213	C	HENPL-RT9635	\$ 31,554	C	\$ 14,900
IO-360-A1A	YES	ENPL-RT9774	\$ 51,752	C	RENPL-RT9774	\$ 34,731	C	HENPL-RT9774	\$ 31,072	C	\$ 14,900
IO-360-A1B	YES	ENPL-RT10287	\$ 51,985	C	RENPL-RT10287	\$ 34,953	C	HENPL-RT10287	\$ 31,294	C	\$ 14,900
IO-360-A1B	YES	ENPL-RT9383	\$ 52,198	C	RENPL-RT9383	\$ 35,156	C	HENPL-RT9383	\$ 31,498	C	\$ 14,900
IO-360-A1B	YES	ENPL-RT9584	\$ 51,980	C	RENPL-RT9584	\$ 34,948	C	HENPL-RT9584	\$ 31,289	C	\$ 14,900
IO-360-A1B	YES	ENPL-RT9937	\$ 51,720	C	RENPL-RT9937	\$ 34,700	C	HENPL-RT9937	\$ 31,042	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10330	\$ 52,910	C	RENPL-RT10330	\$ 35,486	C	HENPL-RT10330	\$ 31,828	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10496	\$ 53,415	C	RENPL-RT10496	\$ 35,335	C	HENPL-RT10496	\$ 31,676	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10587	\$ 52,500	C	RENPL-RT10587	\$ 35,435	C	HENPL-RT10587	\$ 31,777	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10602	\$ 53,024	C	RENPL-RT10602	\$ 35,935	C	HENPL-RT10602	\$ 32,276	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT10693	\$ 54,527	C	RENPL-RT10693	\$ 36,363	C	HENPL-RT10693	\$ 32,705	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8620	\$ 53,410	C	RENPL-RT8620	\$ 36,302	C	HENPL-RT8620	\$ 32,644	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8622	\$ 52,758	C	RENPL-RT8622	\$ 35,957	C	HENPL-RT8622	\$ 32,299	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8669	\$ 53,449	C	RENPL-RT8669	\$ 36,340	C	HENPL-RT8669	\$ 32,681	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8904	\$ 53,082	C	RENPL-RT8904	\$ 35,990	C	HENPL-RT8904	\$ 32,331	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT8915	\$ 53,576	C	RENPL-RT8915	\$ 36,461	C	HENPL-RT8915	\$ 32,803	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9344	\$ 52,320	C	RENPL-RT9344	\$ 35,628	C	HENPL-RT9344	\$ 31,969	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9352	\$ 53,286	C	RENPL-RT9352	\$ 36,184	C	HENPL-RT9352	\$ 32,526	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9362	\$ 54,721	C	RENPL-RT9362	\$ 37,552	C	HENPL-RT9362	\$ 33,894	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9390	\$ 54,204	C	RENPL-RT9390	\$ 37,349	C	HENPL-RT9390	\$ 33,690	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9400	\$ 53,438	C	RENPL-RT9400	\$ 36,330	C	HENPL-RT9400	\$ 32,671	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9503	\$ 53,438	C	RENPL-RT9503	\$ 36,330	C	HENPL-RT9503	\$ 32,671	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9536	\$ 53,163	C	RENPL-RT9536	\$ 36,068	C	HENPL-RT9536	\$ 32,409	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9555	\$ 53,438	C	RENPL-RT9555	\$ 36,330	C	HENPL-RT9555	\$ 32,671	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9737	\$ 54,816	C	RENPL-RT9737	\$ 37,518	C	HENPL-RT9737	\$ 33,860	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9768	\$ 53,353	C	RENPL-RT9768	\$ 36,248	C	HENPL-RT9768	\$ 32,590	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9882	\$ 53,480	C	RENPL-RT9882	\$ 36,369	C	HENPL-RT9882	\$ 32,711	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9896	\$ 51,948	C	RENPL-RT9896	\$ 35,179	C	HENPL-RT9896	\$ 31,521	C	\$ 14,900
IO-360-A1B6	YES	ENPL-RT9943	\$ 53,436	C	RENPL-RT9943	\$ 36,327	C	HENPL-RT9943	\$ 32,669	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT10036	\$ 55,956	C	RENPL-RT10036	\$ 38,730	C	HENPL-RT10036	\$ 35,072	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT5655	\$ 55,848	C	RENPL-RT5655	\$ 38,628	C	HENPL-RT5655	\$ 34,969	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT8074	\$ 55,454	C	RENPL-RT8074	\$ 38,252	C	HENPL-RT8074	\$ 34,593	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT8548	\$ 56,378	C	RENPL-RT8548	\$ 39,133	C	HENPL-RT8548	\$ 35,475	C	\$ 14,900
IO-360-A1B6D	YES	ENPL-RT8586	\$ 56,377	C	RENPL-RT8586	\$ 39,132	C	HENPL-RT8586	\$ 35,473	C	\$ 14,900
IO-360-A1D	YES	ENPL-RT4251	\$ 52,357	C	RENPL-RT4251	\$ 35,299	C	HENPL-RT4251	\$ 31,640	C	\$ 14,900
IO-360-A1D6	YES	ENPL-RT10333	\$ 53,785	C	RENPL-RT10333	\$ 36,660	C	HENPL-RT10333	\$ 33,002	C	\$ 14,900
IO-360-A1D6	YES	ENPL-RT9481	\$ 53,785	C	RENPL-RT9481	\$ 36,661	C	HENPL-RT9481	\$ 33,002	C	\$ 14,900
IO-360-A2B	YES	ENPL-RT8652	\$ 53,479	C	RENPL-RT8652	\$ 36,368	C	HENPL-RT8652	\$ 32,710	C	\$ 14,900
IO-360-A2B	YES	ENPL-RT9759	\$ 53,593	C	RENPL-RT9759	\$ 36,477	C	HENPL-RT9759	\$ 32,819	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT10027	\$ 53,991	C	RENPL-RT10027	\$ 36,857	C	HENPL-RT10027	\$ 33,199	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT10032	\$ 53,953	C	RENPL-RT10032	\$ 36,820	C	HENPL-RT10032	\$ 33,162	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT10502	\$ 54,401	C	RENPL-RT-10502	\$ 37,248	C	HENPL-10502	\$ 33,589	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT9304	\$ 54,426	C	RENPL-RT9304	\$ 37,271	C	HENPL-RT9304	\$ 33,613	C	\$ 14,900
IO-360-A3B6	YES	ENPL-RT9479	\$ 53,614	C	RENPL-RT9479	\$ 36,497	C	HENPL-RT9479	\$ 32,838	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT10070	\$ 57,433	C	RENPL-RT10070	\$ 40,139	C	HENPL-RT10070	\$ 36,481	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT10494	\$ 58,301	C	RENPL-RT10494	\$ 40,966	C	HENPL-RT10494	\$ 37,308	C	\$ 14,900

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
<b>ENGINE MODEL</b>	<b>ROLLER TAPPETS</b>	<b>NEW</b>			<b>REBUILT ("ZERO" TIME)</b>			<b>OVERHAUL</b>			
		<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>CORE VALUE</b>
IO-360-A3B6D	YES	ENPL-RT10519	\$ 56,072	C	RENPL-RT10519	\$ 38,841	C	HENPL-RT10519	\$ 35,183	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT8202	\$ 56,767	C	RENPL-RT8202	\$ 39,814	C	HENPL-RT8202	\$ 36,155	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT8330	\$ 57,891	C	RENPL-RT8330	\$ 40,576	C	HENPL-RT8330	\$ 36,917	C	\$ 14,900
IO-360-A3B6D	YES	ENPL-RT9679	\$ 57,253	C	RENPL-RT9679	\$ 39,967	C	HENPL-RT9679	\$ 36,309	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT8648	\$ 51,134	C	RENPL-RT8648	\$ 34,141	C	HENPL-RT8648	\$ 30,483	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT8895	\$ 51,159	C	RENPL-RT8895	\$ 34,165	C	HENPL-RT8895	\$ 30,506	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT8960	\$ 51,462	C	RENPL-RT8960	\$ 34,454	C	HENPL-RT8960	\$ 30,796	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT9625	\$ 50,748	C	RENPL-RT9625	\$ 33,773	C	HENPL-RT9625	\$ 30,114	C	\$ 14,900
IO-360-B1B	YES	ENPL-RT9904	\$ 50,207	C	RENPL-RT9904	\$ 33,258	C	HENPL-RT9904	\$ 29,599	C	\$ 14,900
IO-360-B1E	YES	ENPL-RT8593	\$ 50,494	C	RENPL-RT8593	\$ 33,531	C	HENPL-RT8593	\$ 29,872	C	\$ 14,900
IO-360-B1E	YES	ENPL-RT8709	\$ 50,419	C	RENPL-RT8709	\$ 33,459	C	HENPL-RT8709	\$ 29,801	C	\$ 14,900
IO-360-B1E	YES	ENPL-RT9747	\$ 50,658	C	RENPL-RT9747	\$ 33,687	C	HENPL-RT9747	\$ 30,029	C	\$ 14,900
IO-360-B1F	YES	ENPL-RT8434	\$ 51,158	C	RENPL-RT8434	\$ 34,164	C	HENPL-RT8434	\$ 30,506	C	\$ 14,900
IO-360-B1F6	YES	ENPL-RT8993	\$ 53,052	C	RENPL-RT8993	\$ 35,970	C	HENPL-RT8993	\$ 32,312	C	\$ 14,900
IO-360-B1G6	YES	ENPL-RT10304	\$ 53,030	C	RENPL-RT10304	\$ 35,950	C	HENPL-RT10304	\$ 32,291	C	\$ 14,900
IO-360-B1G6	YES	ENPL-RT9547	\$ 55,257	C	RENPL-RT9547	\$ 37,048	C	HENPL-RT9547	\$ 33,390	C	\$ 14,900
IO-360-B1G6	YES	ENPL-RT9760	\$ 53,080	C	RENPL-RT9760	\$ 35,997	C	HENPL-RT9760	\$ 32,339	C	\$ 14,900
IO-360-C1B	YES	ENPL-RT8667	\$ 54,176	C	RENPL-RT8667	\$ 37,042	C	HENPL-RT8667	\$ 33,383	C	\$ 14,900
IO-360-C1C	YES	ENPL-RT8612	\$ 51,995	C	RENPL-RT8612	\$ 34,962	C	HENPL-RT8612	\$ 31,304	A	\$ 14,900
IO-360-C1C	YES	ENPL-RT9632	\$ 52,224	C	RENPL-RT9632	\$ 35,181	C	HENPL-RT9632	\$ 31,522	B	\$ 14,900
IO-360-C1C	YES	ENPL-RT9907	\$ 52,863	C	RENPL-RT9907	\$ 35,790	C	HENPL-RT9907	\$ 32,132	B	\$ 14,900
IO-360-C1C	YES	ENPL-RT10019	\$ 51,735	C	RENPL-RT10019	\$ 34,714	C	HENPL-RT10019	\$ 31,055	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT10214	\$ 55,078	C	RENPL-RT10214	\$ 37,902	C	HENPL-RT10214	\$ 34,244	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT10246	\$ 55,230	C	RENPL-RT10246	\$ 38,047	C	HENPL-RT10246	\$ 34,388	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT10540	\$ 54,818	C	RENPL-RT10540	\$ 37,295	C	HENPL-RT10540	\$ 33,636	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT8567	\$ 53,874	C	RENPL-RT8567	\$ 37,040	C	HENPL-RT8567	\$ 33,381	A	\$ 14,900
IO-360-C1C6	YES	ENPL-RT8879	\$ 55,351	C	RENPL-RT8879	\$ 38,162	C	HENPL-RT8879	\$ 34,503	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT9325	\$ 54,865	C	RENPL-RT9325	\$ 37,699	C	HENPL-RT9325	\$ 34,041	B	\$ 14,900
IO-360-C1C6	YES	ENPL-RT9593	\$ 54,083	C	RENPL-RT9593	\$ 36,953	C	HENPL-RT9593	\$ 33,295	B	\$ 14,900
IO-360-C1D6	YES	ENPL-RT10493	\$ 55,822	C	RENPL-RT10493	\$ 38,578	C	HENPL-RT10493	\$ 34,919	C	\$ 14,900
IO-360-C1D6	YES	ENPL-RT9353	\$ 55,275	C	RENPL-RT9353	\$ 38,090	C	HENPL-RT9353	\$ 34,432	C	\$ 14,900
IO-360-C1D6****	YES	ENPL-RT10317	\$ 55,456	C	RENPL-RT10317	\$ 38,262	C	HENPL-RT10317	\$ 34,604	C	\$ 14,900
IO-360-C1E6	YES	ENPL-RT8594	\$ 54,460	C	RENPL-RT8594	\$ 37,313	C	HENPL-RT8594	\$ 33,654	C	\$ 14,900
IO-360-C1F	YES	ENPL-RT9545	\$ 55,262	C	RENPL-RT9545	\$ 38,078	C	HENPL-RT9545	\$ 34,419	C	\$ 14,900
IO-360-C1G6	YES	ENPL-RT9693	\$ 58,321	C	RENPL-RT9693	\$ 40,994	C	HENPL-RT9693	\$ 37,336	C	\$ 14,900
IO-360-L2A	YES	ENPL-RT10230	\$ 50,908	C	RENPL-RT10230	\$ 33,961	C	HENPL-RT10230	\$ 30,303	A	\$ 14,900
IO-360-L2A	YES	ENPL-RT10294	\$ 52,320	C	RENPL-RT10294	\$ 34,365	C	HENPL-RT10294	\$ 30,706	B	\$ 14,900
IO-360-L2A	YES	ENPL-RT10437	\$ 51,095	C	RENPL-RT10437	\$ 34,141	C	HENPL-RT10437	\$ 30,482	B	\$ 14,900
IO-360-L2A	YES	ENPL-RT10596	\$ 50,210	C	RENPL-RT10596	\$ 33,492	C	HENPL-RT10596	\$ 29,833	B	\$ 14,900
IO-360-L2A	YES	ENPL-RT9543	\$ 51,387	C	RENPL-RT9543	\$ 34,418	C	HENPL-RT9543	\$ 30,759	A	\$ 14,900
IO-360-L2A	YES	ENPL-RT9918	\$ 51,342	C	RENPL-RT9918	\$ 34,936	C	HENPL-RT9918	\$ 31,277	B	\$ 14,900
IO-360-M1A	YES	ENPL-RT10051	\$ 50,316	C	RENPL-RT10051	\$ 33,361	C	HENPL-RT10051	\$ 29,703	C	\$ 14,900
IO-360-M1A	YES	ENPL-RT10623	\$ 50,442	C	RENPL-RT10623	\$ 33,481	C	HENPL-RT10623	\$ 29,823	C	\$ 14,900
IO-360-M1B	YES	ENPL-RT10117	\$ 49,200	C	RENPL-RT10117	\$ 32,298	C	HENPL-RT10117	\$ 28,639	C	\$ 14,900
IO-360-M1B	YES	ENPL-RT10167	\$ 50,336	C	RENPL-RT10167	\$ 32,919	C	HENPL-RT10167	\$ 29,260	C	\$ 14,900
LIO-360-C1E6	YES	ENPL-RT8598	\$ 55,358	C	RENPL-RT8598	\$ 38,170	C	HENPL-RT8598	\$ 34,511	C	\$ 14,900
LIO-360-M1A	YES	ENPL-RT10591	\$ 51,581	C	RENPL-RT10591	\$ 34,561	C	HENPL-RT10591	\$ 30,902	C	\$ 14,900
LO-360-A1G6D	YES	ENPL-RT8552	\$ 49,381	C	RENPL-RT8552	\$ 33,940	C	HENPL-RT8552	\$ 30,282	C	\$ 13,900
LO-360-A1G6D	YES	ENPL-RT8672	\$ 49,384	C	RENPL-RT8672	\$ 33,943	C	HENPL-RT8672	\$ 30,285	C	\$ 13,900
LO-360-A1H6	YES	ENPL-RT10570	\$ 47,301	C	RENPL-RT10570	\$ 31,956	C	HENPL-RT10570	\$ 28,298	A	\$ 13,900
LO-360-A1H6	YES	ENPL-RT10679	\$ 47,719	C	RENPL-RT10679	\$ 32,355	C	HENPL-RT10679	\$ 28,697	A	\$ 13,900
LO-360-A1H6	YES	ENPL-RT8496	\$ 47,632	C	RENPL-RT8496	\$ 32,272	C	HENPL-RT8496	\$ 28,614	A	\$ 13,900
LO-360-E1A6D	N/A	ENPL-6719	\$ 49,687	C	RENPL-6719	\$ 34,232	C	HENPL-6719	\$ 30,573	A	\$ 13,900
LO-360-E1A6D**	N/A	ENPL-10223	\$ 49,212	C	RENPL-10223	\$ 34,328	C	HENPL-10223	\$ 30,670	B	\$ 13,900
LTO-360-E1A6D	N/A	ENPL-6948	\$ 71,875	D	RENPL-6948	\$ 53,120	D	HENPL-6948	\$ 47,632	D	\$ 17,000

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
<b>ENGINE MODEL</b>	<b>ROLLER TAPPETS</b>	<b>NEW</b>			<b>REBUILT ("ZERO" TIME)</b>			<b>OVERHAUL</b>			<b>CORE VALUE</b>
		<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	
O-360-A1A	YES	ENPL-RT10101	\$ 44,235	C	RENPL-RT10101	\$ 29,033	C	HENPL-RT10101	\$ 25,375	C	\$ 13,900
O-360-A1A	YES	ENPL-RT10183	\$ 43,912	C	RENPL-RT10183	\$ 28,726	C	HENPL-RT10183	\$ 25,067	C	\$ 13,900
O-360-A1A	YES	ENPL-RT10286	\$ 44,175	C	RENPL-RT10286	\$ 28,976	C	HENPL-RT10286	\$ 25,317	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8435	\$ 44,654	C	RENPL-RT8435	\$ 29,433	C	HENPL-RT8435	\$ 25,775	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8597	\$ 44,229	C	RENPL-RT8597	\$ 29,027	C	HENPL-RT8597	\$ 25,369	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8681	\$ 44,836	C	RENPL-RT8681	\$ 29,607	C	HENPL-RT8681	\$ 25,948	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8683	\$ 44,149	C	RENPL-RT8683	\$ 28,952	C	HENPL-RT8683	\$ 25,293	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8788	\$ 44,259	C	RENPL-RT8788	\$ 29,056	C	HENPL-RT8788	\$ 25,398	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8794	\$ 44,227	C	RENPL-RT8794	\$ 29,026	C	HENPL-RT8794	\$ 25,368	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8820	\$ 44,823	C	RENPL-RT8820	\$ 29,594	C	HENPL-RT8820	\$ 25,936	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8906	\$ 44,788	C	RENPL-RT8906	\$ 29,560	C	HENPL-RT8906	\$ 25,902	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8913	\$ 44,809	C	RENPL-RT8913	\$ 29,580	C	HENPL-RT8913	\$ 25,922	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8932	\$ 44,288	C	RENPL-RT8932	\$ 29,084	C	HENPL-RT8932	\$ 25,426	C	\$ 13,900
O-360-A1A	YES	ENPL-RT8984	\$ 44,288	C	RENPL-RT8984	\$ 29,084	C	HENPL-RT8984	\$ 25,425	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9347	\$ 44,803	C	RENPL-RT9347	\$ 29,575	C	HENPL-RT9347	\$ 25,917	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9507	\$ 44,229	C	RENPL-RT9507	\$ 29,027	C	HENPL-RT9507	\$ 25,369	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9657	\$ 44,229	C	RENPL-RT9657	\$ 29,003	C	HENPL-RT9657	\$ 25,345	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9689	\$ 44,303	C	RENPL-RT9689	\$ 29,098	C	HENPL-RT9689	\$ 25,439	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9778	\$ 44,994	C	RENPL-RT9778	\$ 29,757	C	HENPL-RT9778	\$ 26,098	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9799	\$ 44,807	C	RENPL-RT9799	\$ 29,579	C	HENPL-RT9799	\$ 25,921	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9807	\$ 44,990	C	RENPL-RT9807	\$ 29,753	C	HENPL-RT9807	\$ 26,094	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9808	\$ 43,200	C	RENPL-RT9808	\$ 28,047	C	HENPL-RT9808	\$ 24,388	C	\$ 13,900
O-360-A1A	YES	ENPL-RT9969	\$ 44,227	C	RENPL-RT9969	\$ 29,026	C	HENPL-RT9969	\$ 25,368	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT10245	\$ 47,287	C	RENPL-RT10245	\$ 31,943	C	HENPL-RT10245	\$ 28,285	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT10581	\$ 47,301	C	RENPL-RT10581	\$ 31,957	C	HENPL-RT10581	\$ 28,298	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT8089	\$ 47,674	C	RENPL-RT8089	\$ 31,872	C	HENPL-RT8089	\$ 28,214	C	\$ 13,900
O-360-A1AD	YES	ENPL-RT8494	\$ 46,771	C	RENPL-RT8494	\$ 31,692	C	HENPL-RT8494	\$ 28,034	C	\$ 13,900
O-360-A1D	YES	ENPL-RT10080	\$ 44,163	C	RENPL-RT10080	\$ 28,965	C	HENPL-RT10080	\$ 25,307	C	\$ 13,900
O-360-A1D	YES	ENPL-RT10085	\$ 44,162	C	RENPL-RT10085	\$ 28,964	C	HENPL-RT10085	\$ 25,305	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8041	\$ 44,662	C	RENPL-RT8041	\$ 29,416	C	HENPL-RT8041	\$ 25,758	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8042	\$ 44,821	C	RENPL-RT8042	\$ 29,567	C	HENPL-RT8042	\$ 25,908	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8313	\$ 44,701	C	RENPL-RT8313	\$ 29,892	C	HENPL-RT8313	\$ 26,234	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8939	\$ 44,126	C	RENPL-RT8939	\$ 28,929	C	HENPL-RT8939	\$ 25,271	C	\$ 13,900
O-360-A1D	YES	ENPL-RT8974	\$ 45,393	C	RENPL-RT8974	\$ 30,138	C	HENPL-RT8974	\$ 26,479	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9527	\$ 44,149	C	RENPL-RT9527	\$ 28,951	C	HENPL-RT9527	\$ 25,293	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9582	\$ 45,546	C	RENPL-RT9582	\$ 30,284	C	HENPL-RT9582	\$ 26,625	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9627	\$ 45,121	C	RENPL-RT9627	\$ 29,878	C	HENPL-RT9627	\$ 26,220	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9697	\$ 45,546	C	RENPL-RT9697	\$ 30,284	C	HENPL-RT9697	\$ 26,625	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9779	\$ 45,543	C	RENPL-RT9779	\$ 30,280	C	HENPL-RT9779	\$ 26,622	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9798	\$ 44,770	C	RENPL-RT9798	\$ 29,544	C	HENPL-RT9798	\$ 25,885	C	\$ 13,900
O-360-A1D	YES	ENPL-RT9865	\$ 44,858	C	RENPL-RT9865	\$ 29,628	C	HENPL-RT9865	\$ 25,969	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT10501	\$ 46,185	C	RENPL-RT10501	\$ 30,893	C	HENPL-RT10501	\$ 27,235	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT9316	\$ 45,856	C	RENPL-RT9316	\$ 30,555	C	HENPL-RT9316	\$ 26,897	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT9356	\$ 45,619	C	RENPL-RT9356	\$ 30,353	C	HENPL-RT9356	\$ 26,694	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT9529	\$ 46,035	C	RENPL-RT9529	\$ 30,676	C	HENPL-RT9529	\$ 27,017	C	\$ 13,900
O-360-A1F6	YES	ENPL-RT9666	\$ 45,775	C	RENPL-RT9666	\$ 30,502	C	HENPL-RT9666	\$ 26,843	C	\$ 13,900
O-360-A1F6D	YES	ENPL-RT5654	\$ 48,154	C	RENPL-RT5654	\$ 32,770	C	HENPL-RT5654	\$ 29,111	C	\$ 13,900
O-360-A1F6D	YES	ENPL-RT8105	\$ 48,067	C	RENPL-RT8105	\$ 32,688	C	HENPL-RT8105	\$ 29,029	C	\$ 13,900
O-360-A1G6D	YES	ENPL-RT10661	\$ 48,934	C	RENPL-RT10661	\$ 33,514	C	HENPL-RT10661	\$ 29,855	C	\$ 13,900
O-360-A1G6D	YES	ENPL-RT8045	\$ 48,422	C	RENPL-RT8045	\$ 33,025	C	HENPL-RT8045	\$ 29,367	C	\$ 13,900
O-360-A1G6D	YES	ENPL-RT8671	\$ 48,419	C	RENPL-RT8671	\$ 33,023	C	HENPL-RT8671	\$ 29,364	C	\$ 13,900
O-360-A1H6	YES	ENPL-RT10678	\$ 46,549	C	RENPL-RT10678	\$ 31,239	C	HENPL-RT10678	\$ 27,581	A	\$ 13,900
O-360-A1H6	YES	ENPL-RT8495	\$ 46,462	C	RENPL-RT8495	\$ 31,156	C	HENPL-RT8495	\$ 27,498	A	\$ 13,900
O-360-A1LD	YES	ENPL-RT9618	\$ 46,323	C	RENPL-RT9618	\$ 31,024	C	HENPL-RT9618	\$ 27,366	C	\$ 13,900
O-360-A1P	YES	ENPL-RT9334	\$ 44,397	C	RENPL-RT9334	\$ 29,188	C	HENPL-RT9334	\$ 25,529	C	\$ 13,900

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
O-360-A1P	YES	ENPL-RT9437	\$ 45,071	C	RENPL-RT9437	\$ 29,830	C	HENPL-RT9437	\$ 26,171	C	\$ 13,900
O-360-A1P	YES	ENPL-RT9940	\$ 44,553	C	RENPL-RT9940	\$ 29,337	C	HENPL-RT9940	\$ 25,678	C	\$ 13,900
O-360-A2A	YES	ENPL-RT8536	\$ 45,532	C	RENPL-RT8536	\$ 30,270	C	HENPL-RT8536	\$ 26,612	C	\$ 13,900
O-360-A2A	YES	ENPL-RT8613	\$ 45,076	C	RENPL-RT8613	\$ 29,835	C	HENPL-RT8613	\$ 26,177	C	\$ 13,900
O-360-A2A	YES	ENPL-RT8674	\$ 43,931	C	RENPL-RT8674	\$ 28,743	C	HENPL-RT8674	\$ 25,084	C	\$ 13,900
O-360-A2F	YES	ENPL-RT9378	\$ 44,359	C	RENPL-RT9378	\$ 29,152	C	HENPL-RT9378	\$ 25,493	C	\$ 13,900
O-360-A2F	YES	ENPL-RT9996	\$ 44,386	C	RENPL-RT9996	\$ 29,178	C	HENPL-RT9996	\$ 25,519	C	\$ 13,900
O-360-A2G	YES	ENPL-RT8575	\$ 44,760	C	RENPL-RT8575	\$ 29,534	C	HENPL-RT8575	\$ 25,875	C	\$ 13,900
O-360-A3A	YES	ENPL-RT10159	\$ 45,031	C	RENPL-RT10159	\$ 29,792	C	HENPL-RT10159	\$ 26,134	C	\$ 13,900
O-360-A3A	YES	ENPL-RT10527	\$ 44,159	C	RENPL-RT10527	\$ 29,300	C	HENPL-RT10527	\$ 25,642	C	\$ 13,900
O-360-A3A	YES	ENPL-RT8599	\$ 43,930	C	RENPL-RT8599	\$ 28,839	C	HENPL-RT8599	\$ 25,181	C	\$ 13,900
O-360-A3A	YES	ENPL-RT8614	\$ 44,554	C	RENPL-RT8614	\$ 29,337	C	HENPL-RT8614	\$ 25,679	C	\$ 13,900
O-360-A3A	YES	ENPL-RT8734	\$ 43,749	C	RENPL-RT8734	\$ 29,025	C	HENPL-RT8734	\$ 25,366	C	\$ 13,900
O-360-A3A	YES	ENPL-RT8771	\$ 44,597	C	RENPL-RT8771	\$ 29,378	C	HENPL-RT8771	\$ 25,720	C	\$ 13,900
O-360-A3A	YES	ENPL-RT9656	\$ 44,083	C	RENPL-RT9656	\$ 28,888	C	HENPL-RT9656	\$ 25,230	C	\$ 13,900
O-360-A3A	YES	ENPL-RT9838	\$ 44,581	C	RENPL-RT9838	\$ 29,363	C	HENPL-RT9838	\$ 25,705	C	\$ 13,900
O-360-A3A	YES	ENPL-RT10357	\$ 44,218	C	RENPL-RT10357	\$ 29,017	C	HENPL-RT10357	\$ 25,359	C	\$ 13,900
O-360-A3A	YES	ENPL-RT9633	\$ 44,146	C	RENPL-RT9633	\$ 29,505	C	HENPL-RT9633	\$ 25,847	C	\$ 13,900
O-360-A3AD	YES	ENPL-RT8660	\$ 46,144	C	RENPL-RT8660	\$ 30,854	C	HENPL-RT8660	\$ 27,195	C	\$ 13,900
O-360-A4A	YES	ENPL-RT8601	\$ 43,406	C	RENPL-RT8601	\$ 28,424	C	HENPL-RT8601	\$ 24,765	C	\$ 13,900
O-360-A4A	YES	ENPL-RT9652	\$ 44,176	C	RENPL-RT9652	\$ 28,977	C	HENPL-RT9652	\$ 25,318	C	\$ 13,900
O-360-A4A	YES	ENPL-RT9869	\$ 44,339	C	RENPL-RT9869	\$ 29,133	C	HENPL-RT9869	\$ 25,474	C	\$ 13,900
O-360-A4G	YES	ENPL-RT9361	\$ 44,278	C	RENPL-RT9361	\$ 29,074	C	HENPL-RT9361	\$ 25,416	C	\$ 13,900
O-360-A4J	YES	ENPL-RT10056	\$ 43,728	C	RENPL-RT10056	\$ 28,550	C	HENPL-RT10056	\$ 24,891	C	\$ 13,900
O-360-A4J	YES	ENPL-RT9340	\$ 44,173	C	RENPL-RT9340	\$ 28,974	C	HENPL-RT9340	\$ 25,316	C	\$ 13,900
O-360-A4K	YES	ENPL-RT10196	\$ 45,968	C	RENPL-RT10196	\$ 30,686	C	HENPL-RT10196	\$ 27,027	C	\$ 13,900
O-360-A4K	YES	ENPL-RT8053	\$ 44,182	C	RENPL-RT8053	\$ 28,983	C	HENPL-RT8053	\$ 25,325	C	\$ 13,900
O-360-A4K	YES	ENPL-RT8054	\$ 44,068	C	RENPL-RT8054	\$ 28,874	C	HENPL-RT8054	\$ 25,216	C	\$ 13,900
O-360-A4K	YES	ENPL-RT8056	\$ 44,161	C	RENPL-RT8056	\$ 28,963	C	HENPL-RT8056	\$ 25,305	C	\$ 13,900
O-360-A4K	YES	ENPL-RT8845	\$ 44,634	C	RENPL-RT8845	\$ 29,414	C	HENPL-RT8845	\$ 25,755	C	\$ 13,900
O-360-A4K	YES	ENPL-RT9648	\$ 44,222	C	RENPL-RT9648	\$ 29,021	C	HENPL-RT9648	\$ 25,363	C	\$ 13,900
O-360-A4K	YES	ENPL-RT9658	\$ 44,163	C	RENPL-RT9658	\$ 28,964	C	HENPL-RT9658	\$ 25,306	C	\$ 13,900
O-360-A4K	YES	ENPL-RT9871	\$ 43,782	C	RENPL-RT9871	\$ 28,601	C	HENPL-RT9871	\$ 24,943	C	\$ 13,900
O-360-A4K	YES	ENPL-RT9989	\$ 44,920	C	RENPL-RT9989	\$ 29,687	C	HENPL-RT9989	\$ 26,028	C	\$ 13,900
O-360-A4M	YES	ENPL-RT10004	\$ 44,622	C	RENPL-RT10004	\$ 29,403	C	HENPL-RT10004	\$ 25,744	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10052	\$ 43,999	C	RENPL-RT10052	\$ 28,808	C	HENPL-RT10052	\$ 25,149	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10326	\$ 45,103	C	RENPL-RT10326	\$ 29,861	C	HENPL-RT10326	\$ 26,203	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10339	\$ 45,097	C	RENPL-RT10339	\$ 29,858	C	HENPL-RT10339	\$ 26,199	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10386	\$ 44,517	C	RENPL-RT10386	\$ 29,302	C	HENPL-RT10386	\$ 25,643	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10465	\$ 45,103	C	RENPL-RT10465	\$ 29,861	C	HENPL-RT10465	\$ 26,203	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10672	\$ 44,542	C	RENPL-RT10672	\$ 29,326	C	HENPL-RT10672	\$ 25,667	B	\$ 13,900
O-360-A4M	YES	ENPL-RT10734	\$ 44,744	C	RENPL-RT10734	\$ 29,551	C	HENPL-RT10734	\$ 25,892	B	\$ 13,900
O-360-A4M	YES	ENPL-RT8057	\$ 43,655	C	RENPL-RT8057	\$ 28,480	C	HENPL-RT8057	\$ 24,822	A	\$ 13,900
O-360-A4M	YES	ENPL-RT8863	\$ 43,153	C	RENPL-RT8863	\$ 28,002	C	HENPL-RT8863	\$ 24,343	A	\$ 13,900
O-360-A4M	YES	ENPL-RT8883	\$ 43,362	C	RENPL-RT8883	\$ 28,413	C	HENPL-RT8883	\$ 24,754	B	\$ 13,900
O-360-A4M	YES	ENPL-RT8884	\$ 44,396	C	RENPL-RT8884	\$ 29,187	C	HENPL-RT8884	\$ 25,529	B	\$ 13,900
O-360-A4M	YES	ENPL-RT8928	\$ 43,989	C	RENPL-RT8928	\$ 28,798	C	HENPL-RT8928	\$ 25,140	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9399	\$ 44,646	C	RENPL-RT9399	\$ 29,426	C	HENPL-RT9399	\$ 25,767	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9440	\$ 44,690	C	RENPL-RT9440	\$ 29,467	C	HENPL-RT9440	\$ 25,808	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9451	\$ 45,162	C	RENPL-RT9451	\$ 29,917	C	HENPL-RT9451	\$ 26,259	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9856	\$ 44,360	C	RENPL-RT9856	\$ 29,152	C	HENPL-RT9856	\$ 25,494	B	\$ 13,900
O-360-A4M	YES	ENPL-RT9890	\$ 44,646	C	RENPL-RT9890	\$ 29,426	C	HENPL-RT9890	\$ 25,767	B	\$ 13,900
O-360-A4N	YES	ENPL-RT8165	\$ 44,720	C	RENPL-RT8165	\$ 29,496	C	HENPL-RT8165	\$ 25,837	C	\$ 13,900
O-360-A4P	YES	ENPL-RT8937	\$ 44,436	C	RENPL-RT8937	\$ 29,225	C	HENPL-RT8937	\$ 25,566	C	\$ 13,900
O-360-A5AD	YES	ENPL-RT8226	\$ 42,841	C	RENPL-RT8226	\$ 27,704	C	HENPL-RT8226	\$ 24,045	C	\$ 13,900

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	CORE VALUE
O-360-C1E	YES	ENPL-RT8947	\$ 44,844	C	RENPL-RT8947	\$ 29,614	C	HENPL-RT8947	\$ 25,955	C	\$ 13,900
O-360-C1E	YES	ENPL-RT9797	\$ 44,977	C	RENPL-RT9797	\$ 29,741	C	HENPL-RT9797	\$ 26,083	C	\$ 13,900
O-360-C1F	YES	ENPL-RT8284	\$ 45,006	C	RENPL-RT8284	\$ 29,768	C	HENPL-RT8284	\$ 26,110	C	\$ 13,900
O-360-C1G	YES	ENPL-RT10043	\$ 44,623	C	RENPL-RT10043	\$ 29,404	C	HENPL-RT10043	\$ 25,745	C	\$ 13,900
O-360-C1G	YES	ENPL-RT8427	\$ 44,523	C	RENPL-RT8427	\$ 29,308	C	HENPL-RT8427	\$ 25,650	C	\$ 13,900
O-360-C1G	YES	ENPL-RT9499	\$ 45,060	C	RENPL-RT9499	\$ 29,819	C	HENPL-RT9499	\$ 26,161	C	\$ 13,900
O-360-C2A	YES	ENPL-RT8257	\$ 44,456	C	RENPL-RT8257	\$ 29,244	C	HENPL-RT8257	\$ 25,585	C	\$ 13,900
O-360-C2E	YES	ENPL-RT8262	\$ 44,677	C	RENPL-RT8262	\$ 29,455	C	HENPL-RT8262	\$ 25,796	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9610	\$ 44,663	C	RENPL-RT9610	\$ 29,441	C	HENPL-RT9610	\$ 25,783	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9745	\$ 44,831	C	RENPL-RT9745	\$ 29,602	C	HENPL-RT9745	\$ 25,943	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9764	\$ 44,831	C	RENPL-RT9764	\$ 29,602	C	HENPL-RT9764	\$ 25,943	C	\$ 13,900
O-360-C2E	YES	ENPL-RT9824	\$ 44,810	C	RENPL-RT9824	\$ 29,582	C	HENPL-RT9824	\$ 25,923	C	\$ 13,900
O-360-C4F	YES	ENPL-RT10408	\$ 46,022	C	RENPL-RT10408	\$ 30,457	C	HENPL-RT10408	\$ 26,799	C	\$ 13,900
O-360-C4F	YES	ENPL-RT8986	\$ 44,861	C	RENPL-RT8986	\$ 29,630	C	HENPL-RT8986	\$ 25,972	C	\$ 13,900
O-360-C4P	YES	ENPL-RT10145	\$ 43,546	C	RENPL-RT10145	\$ 28,376	C	HENPL-RT10145	\$ 24,718	C	\$ 13,900
O-360-C4P	YES	ENPL-RT9394	\$ 43,815	C	RENPL-RT9394	\$ 28,633	C	HENPL-RT9394	\$ 24,974	C	\$ 13,900
O-360-E1A6D	N/A	ENPL-6650	\$ 48,945	C	RENPL-6650	\$ 33,525	C	HENPL-6650	\$ 29,866	A	\$ 13,900
O-360-E1A6D	N/A	ENPL-9853	\$ 49,276	C	RENPL-9853	\$ 33,840	C	HENPL-9853	\$ 30,181	B	\$ 13,900
O-360-E1A6D**	N/A	ENPL-10222	\$ 48,404	C	RENPL-10222	\$ 33,544	C	HENPL-10222	\$ 29,886	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT10504	\$ 45,845	C	RENPL-RT10504	\$ 30,568	C	HENPL-RT10504	\$ 26,909	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT8166	\$ 45,844	C	RENPL-RT8166	\$ 30,568	C	HENPL-RT8166	\$ 26,909	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT8898	\$ 45,736	C	RENPL-RT8898	\$ 30,464	C	HENPL-RT8898	\$ 26,806	A	\$ 13,900
O-360-F1A6	YES	ENPL-RT9845	\$ 46,423	C	RENPL-RT9845	\$ 31,120	C	HENPL-RT9845	\$ 27,461	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT9903	\$ 46,489	C	RENPL-RT9903	\$ 31,183	C	HENPL-RT9903	\$ 27,524	B	\$ 13,900
O-360-F1A6	YES	ENPL-RT9917	\$ 46,583	C	RENPL-RT9917	\$ 31,272	C	HENPL-RT9917	\$ 27,614	B	\$ 13,900
O-360-J2A	YES	ENPL-RT10155	\$ 43,828	C	RENPL-RT10155	\$ 29,708	C	HENPL-RT10155	\$ 26,050	C	\$ 13,900
O-360-J2A	YES	ENPL-RT10200	\$ 43,828	C	RENPL-RT10200	\$ 29,708	C	HENPL-RT10200	\$ 26,050	C	\$ 13,900
O-360-J2A	YES	ENPL-RT10603	\$ 43,828	C	RENPL-RT10603	\$ 29,581	C	HENPL-RT10603	\$ 25,922	C	\$ 13,900
TIO-360-C1A6D	N/A	ENPL-8327	\$ 84,168	D	RENPL-8327	\$ 64,888	D	HENPL-8327	\$ 59,400	D	\$ 17,000
TIO-360-C1A6D	N/A	ENPL-9930	\$ 84,827	D	RENPL-9930	\$ 65,517	D	HENPL-9930	\$ 60,029	D	\$ 17,000
TO-360-C1A6D	N/A	ENPL-7322	\$ 75,286	D	RENPL-7322	\$ 56,419	D	HENPL-7322	\$ 50,931	D	\$ 17,000
TO-360-C1A6D	N/A	ENPL-9748	\$ 75,825	D	RENPL-9748	\$ 56,933	D	HENPL-9748	\$ 51,445	D	\$ 17,000
TO-360-E1A6D	N/A	ENPL-6947	\$ 70,603	D	RENPL-6947	\$ 51,954	D	HENPL-6947	\$ 46,466	D	\$ 17,000
IO-390-A1A6	YES	ENPL-RT10620	\$ 57,313	C	RENPL-RT10620	\$ 40,913	C	HENPL-RT10620	\$ 37,255	C	\$ 15,900
AEIO-540-D4A5	YES	ENPL-RT10144	\$ 72,240	C	RENPL-RT10144	\$ 51,235	C	HENPL-RT10144	\$ 46,967	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT10285	\$ 70,288	C	RENPL-RT10285	\$ 49,374	C	HENPL-RT10285	\$ 45,106	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT8318	\$ 71,719	C	RENPL-RT8318	\$ 50,738	C	HENPL-RT8318	\$ 46,470	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT8417	\$ 69,351	C	RENPL-RT8417	\$ 48,481	C	HENPL-RT8417	\$ 44,212	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT8515	\$ 69,886	C	RENPL-RT8515	\$ 48,991	C	HENPL-RT8515	\$ 44,722	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9339	\$ 71,194	C	RENPL-RT9339	\$ 50,238	C	HENPL-RT9339	\$ 45,970	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9406	\$ 70,861	C	RENPL-RT9406	\$ 49,921	C	HENPL-RT9406	\$ 45,652	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9442	\$ 70,010	C	RENPL-RT9442	\$ 49,109	C	HENPL-RT9442	\$ 44,841	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9445	\$ 72,240	C	RENPL-RT9445	\$ 51,235	C	HENPL-RT9445	\$ 46,967	C	\$ 17,600
AEIO-540-D4A5	YES	ENPL-RT9783	\$ 70,433	C	RENPL-RT9783	\$ 49,513	C	HENPL-RT9783	\$ 45,244	C	\$ 17,600
AEIO-540-D4B5	YES	ENPL-RT8768	\$ 70,114	C	RENPL-RT8768	\$ 49,208	C	HENPL-RT8768	\$ 44,940	C	\$ 17,600
AEIO-540-D4B5	YES	ENPL-RT8836	\$ 68,594	C	RENPL-RT8836	\$ 47,759	C	HENPL-RT8836	\$ 43,490	C	\$ 17,600
AEIO-540-D4D5	YES	ENPL-RT9512	\$ 75,310	C	RENPL-RT9512	\$ 54,163	C	HENPL-RT9512	\$ 49,895	C	\$ 17,600
AEIO-540-L1B5	YES	ENPL-RT8544	\$ 75,925	C	RENPL-RT8544	\$ 51,599	C	HENPL-RT8544	\$ 47,330	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT8985	\$ 77,143	C	RENPL-RT8985	\$ 52,760	C	HENPL-RT8985	\$ 48,492	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT9566	\$ 77,166	C	RENPL-RT9566	\$ 52,781	C	HENPL-RT9566	\$ 48,513	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT9609	\$ 75,290	C	RENPL-RT9609	\$ 50,993	C	HENPL-RT9609	\$ 46,725	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT9893	\$ 77,120	C	RENPL-RT9893	\$ 52,737	C	HENPL-RT9893	\$ 48,469	C	\$ 19,900
AEIO-540-L1B5	YES	ENPL-RT9899	\$ 77,206	C	RENPL-RT9899	\$ 52,820	C	HENPL-RT9899	\$ 48,551	C	\$ 19,900
AEIO-540-L1B5D	YES	ENPL-RT7362	\$ 78,063	C	RENPL-RT7362	\$ 53,637	C	HENPL-RT7362	\$ 49,368	C	\$ 19,900
AEIO-540-L1B5D	YES	ENPL-RT7432	\$ 78,705	C	RENPL-RT7432	\$ 54,249	D	HENPL-RT7432	\$ 49,981	C	\$ 19,900

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST  
Effective January 1, 2012  
(Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
AEIO-540-L1B5D	YES	ENPL-RT7471	\$ 78,704	C	RENPL-RT7471	\$ 54,248	D	HENPL-RT7471	\$ 49,980	D	\$ 19,900
AEIO-540-L1D5	YES	ENPL-RT10088	\$ 77,166	C	RENPL-RT10088	\$ 52,781	D	HENPL-RT10088	\$ 48,513	D	\$ 19,900
IO-540-AA1A5	YES	ENPL-RT10224	\$ 76,210	C	RENPL-RT10224	\$ 55,020	C	HENPL-RT10224	\$ 50,752	C	\$ 17,600
IO-540-AA1A5	YES	ENPL-RT8481	\$ 75,864	C	RENPL-RT8481	\$ 54,691	C	HENPL-RT8481	\$ 50,423	C	\$ 17,600
IO-540-AA1B5	YES	ENPL-RT8873	\$ 69,737	C	RENPL-RT8873	\$ 48,848	C	HENPL-RT8873	\$ 44,580	C	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT10221	\$ 70,341	C	RENPL-RT10221	\$ 49,425	C	HENPL-RT10221	\$ 45,156	B	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT10231	\$ 70,266	C	RENPL-RT10231	\$ 49,353	C	HENPL-RT10231	\$ 45,085	A	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT10438	\$ 70,582	C	RENPL-RT10438	\$ 49,657	C	HENPL-RT10438	\$ 45,388	A	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT10597	\$ 69,614	C	RENPL-RT10597	\$ 48,913	C	HENPL-RT10597	\$ 44,644	A	\$ 17,600
IO-540-AB1A5	YES	ENPL-RT9544	\$ 69,555	C	RENPL-RT9544	\$ 48,675	C	HENPL-RT9544	\$ 44,407	A	\$ 17,600
IO-540-AC1A5	YES	ENPL-RT10148	\$ 78,677	C	RENPL-RT10148	\$ 57,373	C	HENPL-RT10148	\$ 53,105	A	\$ 17,600
IO-540-AC1A5	YES	ENPL-RT10598	\$ 78,029	C	RENPL-RT10598	\$ 56,900	C	HENPL-RT10598	\$ 52,632	A	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10160	\$ 75,903	C	RENPL-RT10160	\$ 54,728	C	HENPL-RT10160	\$ 50,460	C	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10202	\$ 75,903	C	RENPL-RT10202	\$ 54,728	C	HENPL-RT10202	\$ 50,460	C	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10278	\$ 75,903	C	RENPL-RT10278	\$ 54,728	C	HENPL-RT10278	\$ 50,460	C	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10293	\$ 75,655	C	RENPL-RT10293	\$ 54,491	C	HENPL-RT10293	\$ 50,223	C	\$ 17,600
IO-540-AE1A5	YES	ENPL-RT10356	\$ 75,909	C	RENPL-RT10356	\$ 54,734	C	HENPL-RT10356	\$ 50,465	C	\$ 17,600
IO-540-C1B5	YES	ENPL-RT9954	\$ 65,722	C	RENPL-RT9954	\$ 45,020	C	HENPL-RT9954	\$ 40,752	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT10099	\$ 65,090	C	RENPL-RT10099	\$ 44,418	C	HENPL-RT10099	\$ 40,149	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT10523	\$ 65,270	C	RENPL-RT10523	\$ 44,590	C	HENPL-RT10523	\$ 40,321	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT10653	\$ 65,379	C	RENPL-RT10653	\$ 44,693	C	HENPL-RT10653	\$ 40,425	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT10710	\$ 65,910	C	RENPL-RT10710	\$ 45,199	C	HENPL-RT10710	\$ 40,931	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8303	\$ 65,746	C	RENPL-RT8303	\$ 45,043	C	HENPL-RT8303	\$ 40,775	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8390	\$ 65,877	C	RENPL-RT8390	\$ 45,168	C	HENPL-RT8390	\$ 40,900	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8458	\$ 65,877	C	RENPL-RT8458	\$ 45,168	C	HENPL-RT8458	\$ 40,899	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8602	\$ 65,708	C	RENPL-RT8602	\$ 45,006	C	HENPL-RT8602	\$ 40,738	A	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8621	\$ 65,722	C	RENPL-RT8621	\$ 45,020	C	HENPL-RT8621	\$ 40,752	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT8991	\$ 65,694	C	RENPL-RT8991	\$ 44,994	C	HENPL-RT8991	\$ 40,725	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9743	\$ 66,572	C	RENPL-RT9743	\$ 45,830	C	HENPL-RT9743	\$ 41,562	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9762	\$ 67,912	C	RENPL-RT9762	\$ 47,108	C	HENPL-RT9762	\$ 42,840	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9784	\$ 65,708	C	RENPL-RT9784	\$ 45,751	C	HENPL-RT9784	\$ 41,482	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9915	\$ 65,877	C	RENPL-RT9915	\$ 45,168	C	HENPL-RT9915	\$ 40,900	B	\$ 17,600
IO-540-C4B5	YES	ENPL-RT9972	\$ 65,531	C	RENPL-RT9972	\$ 44,838	C	HENPL-RT9972	\$ 40,570	B	\$ 17,600
IO-540-C4D5	YES	ENPL-RT8724	\$ 66,285	C	RENPL-RT8724	\$ 45,557	C	HENPL-RT8724	\$ 41,289	C	\$ 17,600
IO-540-C4D5	YES	ENPL-RT8916	\$ 66,285	C	RENPL-RT8916	\$ 48,812	C	HENPL-RT8916	\$ 44,543	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT10582	\$ 68,122	C	RENPL-RT10582	\$ 47,309	C	HENPL-RT10582	\$ 43,040	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT10692	\$ 67,606	C	RENPL-RT10692	\$ 47,593	C	HENPL-RT10692	\$ 43,325	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT8274	\$ 67,606	C	RENPL-RT8274	\$ 46,817	C	HENPL-RT8274	\$ 42,548	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT8468	\$ 67,526	C	RENPL-RT8468	\$ 46,740	C	HENPL-RT8468	\$ 42,472	C	\$ 17,600
IO-540-C4D5D	YES	ENPL-RT8542	\$ 67,592	C	RENPL-RT8542	\$ 46,803	C	HENPL-RT8542	\$ 42,535	C	\$ 17,600
IO-540-C4D5D*	YES	ENPL-RT10204	\$ 67,508	C	RENPL-RT10204	\$ 45,288	C	HENPL-RT10204	\$ 41,019	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT6926	\$ 65,346	C	RENPL-RT6926	\$ 44,662	C	HENPL-RT6926	\$ 40,394	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT9781	\$ 65,327	C	RENPL-RT9781	\$ 44,643	C	HENPL-RT9781	\$ 40,375	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT9809	\$ 65,457	C	RENPL-RT9809	\$ 44,767	C	HENPL-RT9809	\$ 40,499	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT9942	\$ 65,479	C	RENPL-RT9942	\$ 44,789	C	HENPL-RT9942	\$ 40,520	C	\$ 17,600
IO-540-D4A5	YES	ENPL-RT9979	\$ 64,589	C	RENPL-RT9979	\$ 43,940	C	HENPL-RT9979	\$ 39,671	C	\$ 17,600
IO-540-D4B5	YES	ENPL-RT10394	\$ 66,625	C	RENPL-RT10394	\$ 45,882	C	HENPL-RT10394	\$ 41,613	C	\$ 17,600
IO-540-G1D5	YES	ENPL-RT10416	\$ 73,276	C	RENPL-RT10416	\$ 52,223	C	HENPL-RT10416	\$ 47,955	C	\$ 17,600
IO-540-J4A5	YES	ENPL-RT9816	\$ 69,698	C	RENPL-RT9816	\$ 48,812	C	HENPL-RT9816	\$ 44,543	C	\$ 17,600
IO-540-J4A5	YES	ENPL-RT9962	\$ 69,035	C	RENPL-RT9962	\$ 48,179	C	HENPL-RT9962	\$ 43,911	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT10595	\$ 72,380	C	RENPL-RT10595	\$ 51,369	C	HENPL-RT10595	\$ 47,100	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT10741	\$ 77,859	C	RENPL-RT10741	\$ 55,344	C	HENPL-RT10741	\$ 51,075	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT8679	\$ 73,058	C	RENPL-RT8679	\$ 52,015	C	HENPL-RT8679	\$ 47,747	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT9755	\$ 73,049	C	RENPL-RT9755	\$ 52,007	C	HENPL-RT9755	\$ 47,738	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT9801	\$ 73,366	C	RENPL-RT9801	\$ 52,309	C	HENPL-RT9801	\$ 48,041	C	\$ 17,600

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST  
Effective January 1, 2012  
(Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
IO-540-K1A5	YES	ENPL-RT9862	\$ 72,877	C	RENPL-RT9862	\$ 51,843	C	HENPL-RT9862	\$ 47,575	C	\$ 17,600
IO-540-K1A5	YES	ENPL-RT10761	\$ 73,039	C	RENPL-RT10761	\$ 51,985	C	HENPL-RT10761	\$ 47,717	C	\$ 17,600
IO-540-K1A5D	YES	ENPL-RT8537	\$ 75,726	C	RENPL-RT8537	\$ 54,560	C	HENPL-RT8537	\$ 50,291	C	\$ 17,600
IO-540-K1A5D	YES	ENPL-RT9848	\$ 75,912	C	RENPL-RT9848	\$ 54,737	C	HENPL-RT9848	\$ 50,469	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT10234	\$ 73,887	C	RENPL-RT10234	\$ 52,806	C	HENPL-RT10234	\$ 48,538	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT10248	\$ 73,781	C	RENPL-RT10248	\$ 52,705	C	HENPL-RT10248	\$ 48,437	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT10538	\$ 74,303	C	RENPL-RT10538	\$ 53,203	C	HENPL-RT10538	\$ 48,934	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT8584	\$ 73,549	C	RENPL-RT8584	\$ 52,484	C	HENPL-RT8584	\$ 48,215	C	\$ 17,600
IO-540-K1B5	YES	ENPL-RT9419	\$ 73,648	C	RENPL-RT9419	\$ 52,578	C	HENPL-RT9419	\$ 48,309	C	\$ 17,600
IO-540-K1D5	YES	ENPL-RT8859	\$ 74,177	C	RENPL-RT8859	\$ 53,083	C	HENPL-RT8859	\$ 48,814	C	\$ 17,600
IO-540-K1E5	YES	ENPL-RT9371	\$ 74,017	C	RENPL-RT9371	\$ 52,930	C	HENPL-RT9371	\$ 48,661	C	\$ 17,600
IO-540-K1F5	YES	ENPL-RT10306	\$ 73,115	C	RENPL-RT10306	\$ 52,070	C	HENPL-RT10306	\$ 47,801	C	\$ 17,600
IO-540-K1F5	YES	ENPL-RT6625	\$ 74,926	C	RENPL-RT6625	\$ 53,796	C	HENPL-RT6625	\$ 49,528	C	\$ 17,600
IO-540-K1F5	YES	ENPL-RT9914	\$ 74,266	C	RENPL-RT9914	\$ 53,168	C	HENPL-RT9914	\$ 48,899	C	\$ 17,600
IO-540-K1G5	YES	ENPL-RT10025	\$ 71,025	C	RENPL-RT10025	\$ 50,077	C	HENPL-RT10025	\$ 45,809	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT10324	\$ 70,587	C	RENPL-RT10324	\$ 49,659	C	HENPL-RT10324	\$ 45,391	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT10397	\$ 71,103	C	RENPL-RT10397	\$ 50,151	C	HENPL-RT10397	\$ 45,883	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT10645	\$ 73,335	C	RENPL-RT10645	\$ 52,279	C	HENPL-RT10645	\$ 48,011	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT8426	\$ 71,415	C	RENPL-RT8426	\$ 50,449	C	HENPL-RT8426	\$ 46,181	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT8581	\$ 70,814	C	RENPL-RT8581	\$ 49,875	C	HENPL-RT8581	\$ 45,607	A	\$ 17,600
IO-540-K1G5	YES	ENPL-RT8969	\$ 70,945	C	RENPL-RT8969	\$ 50,001	C	HENPL-RT8969	\$ 45,732	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT8972	\$ 70,631	C	RENPL-RT8972	\$ 49,701	C	HENPL-RT8972	\$ 45,433	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9386	\$ 70,729	C	RENPL-RT9386	\$ 49,795	C	HENPL-RT9386	\$ 45,526	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9591	\$ 73,223	C	RENPL-RT9591	\$ 52,173	C	HENPL-RT9591	\$ 47,905	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9629	\$ 70,952	C	RENPL-RT9629	\$ 50,007	C	HENPL-RT9629	\$ 45,739	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9788	\$ 70,782	C	RENPL-RT9788	\$ 49,846	C	HENPL-RT9788	\$ 45,577	B	\$ 17,600
IO-540-K1G5	YES	ENPL-RT9861	\$ 70,773	C	RENPL-RT9861	\$ 49,837	C	HENPL-RT9861	\$ 45,569	B	\$ 17,600
IO-540-K1G5D	YES	ENPL-RT10331	\$ 72,829	C	RENPL-RT10331	\$ 51,797	C	HENPL-RT10331	\$ 47,529	B	\$ 17,600
IO-540-K1G5D	YES	ENPL-RT8279	\$ 74,255	C	RENPL-RT8279	\$ 53,157	C	HENPL-RT8279	\$ 48,889	A	\$ 17,600
IO-540-K1G5D	YES	ENPL-RT8450	\$ 74,057	C	RENPL-RT8450	\$ 52,968	C	HENPL-RT8450	\$ 48,699	B	\$ 17,600
IO-540-K1G5D	YES	ENPL-RT9889	\$ 73,508	C	RENPL-RT9889	\$ 52,445	C	HENPL-RT9889	\$ 48,177	B	\$ 17,600
IO-540-K1H5	YES	ENPL-RT10114	\$ 73,223	C	RENPL-RT10114	\$ 52,173	C	HENPL-RT10114	\$ 47,905	B	\$ 17,600
IO-540-K1J5	YES	ENPL-RT10229	\$ 72,968	C	RENPL-RT10229	\$ 51,930	C	HENPL-RT10229	\$ 47,662	C	\$ 17,600
IO-540-K1J5	YES	ENPL-RT10305	\$ 63,927	C	RENPL-RT10305	\$ 45,560	C	HENPL-RT10305	\$ 41,292	C	\$ 17,600
IO-540-K1J5	YES	ENPL-RT8892	\$ 72,982	C	RENPL-RT8892	\$ 51,943	C	HENPL-RT8892	\$ 47,675	C	\$ 17,600
IO-540-K1J5D	YES	ENPL-RT8346	\$ 73,814	C	RENPL-RT8346	\$ 52,736	C	HENPL-RT8346	\$ 48,467	C	\$ 17,600
IO-540-K1K5	YES	ENPL-RT8582	\$ 71,628	C	RENPL-RT8582	\$ 50,652	C	HENPL-RT8582	\$ 46,383	C	\$ 17,600
IO-540-L1C5	YES	ENPL-RT9800	\$ 74,270	C	RENPL-RT9800	\$ 53,171	C	HENPL-RT9800	\$ 48,903	C	\$ 17,600
IO-540-M1A5	YES	ENPL-RT8658	\$ 73,405	C	RENPL-RT8658	\$ 52,346	C	HENPL-RT8658	\$ 48,078	C	\$ 17,600
IO-540-M1A5	YES	ENPL-RT9343	\$ 74,310	C	RENPL-RT9343	\$ 53,209	C	HENPL-RT9343	\$ 48,940	C	\$ 17,600
IO-540-M1B5D	YES	ENPL-RT7027	\$ 76,419	C	RENPL-RT7027	\$ 55,221	C	HENPL-RT7027	\$ 50,952	C	\$ 17,600
IO-540-M1C5	YES	ENPL-RT10344	\$ 76,488	C	RENPL-RT10344	\$ 54,479	C	HENPL-RT10344	\$ 50,211	C	\$ 17,600
IO-540-M1C5	YES	ENPL-RT8935	\$ 75,901	C	RENPL-RT8935	\$ 53,919	C	HENPL-RT8935	\$ 49,651	C	\$ 17,600
IO-540-N1A5	YES	ENPL-RT8914	\$ 70,987	C	RENPL-RT8914	\$ 50,040	C	HENPL-RT8914	\$ 45,772	C	\$ 17,600
IO-540-R1A5	YES	ENPL-RT9988	\$ 73,130	C	RENPL-RT9988	\$ 52,084	C	HENPL-RT9988	\$ 47,816	C	\$ 17,600
IO-540-S1A5	YES	ENPL-RT8554	\$ 75,584	C	RENPL-RT8554	\$ 54,424	C	HENPL-RT8554	\$ 50,156	C	\$ 17,600
IO-540-T4A5D	YES	ENPL-RT5243	\$ 72,021	C	RENPL-RT5243	\$ 51,026	C	HENPL-RT5243	\$ 46,758	C	\$ 17,600
IO-540-T4B5	YES	ENPL-RT9641	\$ 66,281	C	RENPL-RT9641	\$ 45,554	C	HENPL-RT9641	\$ 41,285	C	\$ 17,600
IO-540-T4B5	YES	ENPL-RT9766	\$ 66,826	C	RENPL-RT9766	\$ 46,073	C	HENPL-RT9766	\$ 41,805	C	\$ 17,600
IO-540-T4B5	YES	ENPL-RT9785	\$ 66,826	C	RENPL-RT9785	\$ 46,073	C	HENPL-RT9785	\$ 41,805	C	\$ 17,600
IO-540-T4B5D	YES	ENPL-RT8838	\$ 68,693	C	RENPL-RT8838	\$ 47,854	C	HENPL-RT8838	\$ 43,585	C	\$ 17,600
IO-540-V4A5	YES	ENPL-RT10227	\$ 66,767	C	RENPL-RT10227	\$ 46,017	C	HENPL-RT10227	\$ 41,748	C	\$ 17,600
IO-540-V4A5	YES	ENPL-RT10410	\$ 69,537	C	RENPL-RT10410	\$ 48,658	C	HENPL-RT10410	\$ 44,390	C	\$ 17,600
IO-540-V4A5	YES	ENPL-RT9551	\$ 69,228	C	RENPL-RT9551	\$ 48,364	C	HENPL-RT9551	\$ 44,095	C	\$ 17,600
IO-540-V4A5	YES	ENPL-RT9570	\$ 67,347	C	RENPL-RT9570	\$ 46,569	C	HENPL-RT9570	\$ 42,301	C	\$ 17,600

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
<b>ENGINE MODEL</b>	<b>ROLLER TAPPETS</b>	<b>NEW</b>			<b>REBUILT ("ZERO" TIME)</b>			<b>OVERHAUL</b>			<b>CORE VALUE</b>
		<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	
IO-540-W1A5	YES	ENPL-RT9493	\$ 64,474	D	RENPL-RT9493	\$ 43,830	D	HENPL-RT9493	\$ 39,562	D	\$ 17,600
IO-540-W1A5	YES	ENPL-RT9494	\$ 64,591	D	RENPL-RT9494	\$ 43,942	D	HENPL-RT9494	\$ 39,673	D	\$ 17,600
IO-540-W1A5D	YES	ENPL-RT7209	\$ 68,145	D	RENPL-RT7209	\$ 47,331	D	HENPL-RT7209	\$ 43,063	D	\$ 17,600
LTIO-540-F2BD	N/A	ENPL-8200	\$ 96,841	C	RENPL-8200	\$ 70,851	C	HENPL-8200	\$ 64,753	C	\$ 22,000
LTIO-540-J2B	N/A	ENPL-10291	\$ 94,347	C	RENPL-10291	\$ 68,526	C	HENPL-10291	\$ 62,429	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-10297	\$ 94,347	C	RENPL-10297	\$ 68,526	C	HENPL-10297	\$ 62,429	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-8122	\$ 94,349	C	RENPL-8122	\$ 68,528	C	HENPL-8122	\$ 62,430	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-8946	\$ 94,347	C	RENPL-8946	\$ 68,526	C	HENPL-8946	\$ 62,429	B	\$ 22,000
LTIO-540-J2B	N/A	ENPL-9402	\$ 94,349	C	RENPL-9402	\$ 68,528	C	HENPL-9402	\$ 62,430	B	\$ 22,000
LTIO-540-J2BD	N/A	ENPL-8148	\$ 94,979	C	RENPL-8148	\$ 69,056	C	HENPL-8148	\$ 62,958	A	\$ 22,000
LTIO-540-U2A	N/A	ENPL-8650	\$ 103,027	C	RENPL-8650	\$ 66,298	C	HENPL-8650	\$ 60,201	C	\$ 29,400
LTIO-540-U2A	N/A	ENPL-8998	\$ 102,773	C	RENPL-8998	\$ 66,056	C	HENPL-8998	\$ 59,958	C	\$ 29,400
O-540-A1A5	YES	ENPL-RT9888	\$ 55,829	C	RENPL-RT9888	\$ 38,108	C	HENPL-RT9888	\$ 33,840	C	\$ 15,800
O-540-A1B5	YES	ENPL-RT9841	\$ 56,025	C	RENPL-RT9841	\$ 38,295	C	HENPL-RT9841	\$ 34,026	C	\$ 15,800
O-540-A1C5	YES	ENPL-RT9866	\$ 56,105	C	RENPL-RT9866	\$ 38,371	C	HENPL-RT9866	\$ 34,103	C	\$ 15,800
O-540-A1D5	YES	ENPL-RT9840	\$ 56,116	C	RENPL-RT9840	\$ 38,381	C	HENPL-RT9840	\$ 34,113	C	\$ 15,800
O-540-A1D5	YES	ENPL-RT9939	\$ 56,277	C	RENPL-RT9939	\$ 38,534	C	HENPL-RT9939	\$ 34,266	C	\$ 15,800
O-540-A4D5	YES	ENPL-RT10123	\$ 57,182	C	RENPL-RT10123	\$ 39,399	C	HENPL-RT10123	\$ 35,130	C	\$ 15,800
O-540-B1A5	YES	ENPL-RT9811	\$ 57,644	C	RENPL-RT9811	\$ 38,368	C	HENPL-RT9811	\$ 34,100	C	\$ 16,900
O-540-B2B5	YES	ENPL-RT8686	\$ 58,161	C	RENPL-RT8686	\$ 38,861	C	HENPL-RT8686	\$ 34,593	C	\$ 16,900
O-540-B2B5	YES	ENPL-RT9615	\$ 58,940	C	RENPL-RT9615	\$ 39,604	C	HENPL-RT9615	\$ 35,335	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT10030	\$ 61,458	C	RENPL-RT10030	\$ 42,005	C	HENPL-RT10030	\$ 37,736	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT10157	\$ 61,524	C	RENPL-RT10157	\$ 42,067	C	HENPL-RT10157	\$ 37,799	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT8588	\$ 61,471	C	RENPL-RT8588	\$ 42,017	C	HENPL-RT8588	\$ 37,749	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT9484	\$ 61,642	C	RENPL-RT9484	\$ 42,180	C	HENPL-RT9484	\$ 37,912	C	\$ 16,900
O-540-B2C5	YES	ENPL-RT9953	\$ 61,790	C	RENPL-RT9953	\$ 42,321	C	HENPL-RT9953	\$ 38,053	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT9359	\$ 57,841	C	RENPL-RT9359	\$ 38,555	C	HENPL-RT9359	\$ 34,287	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT9491	\$ 58,683	C	RENPL-RT9491	\$ 39,359	C	HENPL-RT9491	\$ 35,091	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT9594	\$ 58,722	C	RENPL-RT9594	\$ 39,396	C	HENPL-RT9594	\$ 35,128	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT9879	\$ 57,329	C	RENPL-RT9879	\$ 38,232	C	HENPL-RT9879	\$ 33,964	C	\$ 16,900
O-540-B4B5	YES	ENPL-RT10358	\$ 58,324	C	RENPL-RT10358	\$ 39,016	C	HENPL-RT10358	\$ 34,748	C	\$ 16,900
O-540-E4A5	YES	ENPL-RT8395	\$ 57,982	C	RENPL-RT8395	\$ 38,690	C	HENPL-RT8395	\$ 34,422	C	\$ 16,900
O-540-E4A5	YES	ENPL-RT8514	\$ 57,879	C	RENPL-RT8514	\$ 38,592	C	HENPL-RT8514	\$ 34,324	C	\$ 16,900
O-540-E4A5	YES	ENPL-RT9444	\$ 58,969	C	RENPL-RT9444	\$ 39,632	C	HENPL-RT9444	\$ 35,363	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10008	\$ 58,044	C	RENPL-RT10008	\$ 38,749	C	HENPL-RT10008	\$ 34,481	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10044	\$ 57,465	C	RENPL-RT10044	\$ 38,197	C	HENPL-RT10044	\$ 33,929	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10075	\$ 57,624	C	RENPL-RT10075	\$ 38,348	C	HENPL-RT10075	\$ 34,080	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10079	\$ 57,648	C	RENPL-RT10079	\$ 38,371	C	HENPL-RT10079	\$ 34,103	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT10550	\$ 57,555	C	RENPL-RT10550	\$ 38,450	C	HENPL-RT10550	\$ 34,181	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT8655	\$ 57,623	C	RENPL-RT8655	\$ 38,348	C	HENPL-RT8655	\$ 34,080	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT8890	\$ 58,056	C	RENPL-RT8890	\$ 38,760	C	HENPL-RT8890	\$ 34,492	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT9690	\$ 58,385	C	RENPL-RT9690	\$ 39,074	C	HENPL-RT9690	\$ 34,806	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT9825	\$ 58,038	C	RENPL-RT9825	\$ 38,744	C	HENPL-RT9825	\$ 34,476	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT9961	\$ 58,002	C	RENPL-RT9961	\$ 38,709	C	HENPL-RT9961	\$ 34,441	C	\$ 16,900
O-540-E4B5	YES	ENPL-RT9886	\$ 57,658	C	RENPL-RT9886	\$ 38,381	C	HENPL-RT9886	\$ 34,113	C	\$ 16,900
O-540-E4C5	YES	ENPL-RT10132	\$ 57,483	C	RENPL-RT10132	\$ 38,215	C	HENPL-RT10132	\$ 33,947	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT8566	\$ 58,184	C	RENPL-RT8566	\$ 38,882	C	HENPL-RT8566	\$ 34,614	A	\$ 16,900
O-540-E4C5	YES	ENPL-RT9538	\$ 57,034	C	RENPL-RT9538	\$ 37,786	C	HENPL-RT9538	\$ 33,518	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9736	\$ 57,812	C	RENPL-RT9736	\$ 38,528	C	HENPL-RT9736	\$ 34,260	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9885	\$ 57,499	C	RENPL-RT9885	\$ 38,230	C	HENPL-RT9885	\$ 33,962	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9928	\$ 57,495	C	RENPL-RT9928	\$ 38,226	C	HENPL-RT9928	\$ 33,958	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9931	\$ 58,167	C	RENPL-RT9931	\$ 38,867	C	HENPL-RT9931	\$ 34,599	B	\$ 16,900
O-540-E4C5	YES	ENPL-RT9998	\$ 57,544	C	RENPL-RT9998	\$ 38,272	C	HENPL-RT9998	\$ 34,004	B	\$ 16,900
O-540-F1B5	YES	ENPL-RT10140	\$ 59,583	C	RENPL-RT10140	\$ 40,217	C	HENPL-RT10140	\$ 35,948	C	\$ 16,900
O-540-F1B5	YES	ENPL-RT10220	\$ 59,583	C	RENPL-RT10220	\$ 40,528	C	HENPL-RT10220	\$ 36,259	C	\$ 16,900

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

**LYCOMING AFTERMARKET ENGINE PRICE LIST**  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURERS SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
<b>ENGINE MODEL</b>	<b>ROLLER TAPPETS</b>	<b>NEW</b>			<b>REBUILT ("ZERO" TIME)</b>			<b>OVERHAUL</b>			<b>CORE VALUE</b>
		<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	<b>PART NO.</b>	<b>MSRP</b>	<b>DC</b>	
O-540-F1B5	YES	ENPL-RT10292	\$ 59,583	C	RENPL-RT10292	\$ 40,392	C	HENPL-RT10292	\$ 36,124	C	\$ 16,900
O-540-F1B5	YES	ENPL-RT10599	\$ 59,288	C	RENPL-RT10599	\$ 40,216	C	HENPL-RT10599	\$ 35,948	C	\$ 16,900
O-540-F1B5	YES	ENPL-RT9793	\$ 59,583	C	RENPL-RT9793	\$ 40,528	C	HENPL-RT9793	\$ 36,259	C	\$ 16,900
O-540-G1A5	YES	ENPL-RT8583	\$ 60,461	C	RENPL-RT8583	\$ 41,054	C	HENPL-RT8583	\$ 36,786	C	\$ 16,900
O-540-H2A5	YES	ENPL-RT8480	\$ 60,460	C	RENPL-RT8480	\$ 41,054	C	HENPL-RT8480	\$ 36,786	C	\$ 16,900
O-540-J1A5D	YES	ENPL-RT7208	\$ 58,739	C	RENPL-RT7208	\$ 39,413	C	HENPL-RT7208	\$ 35,144	C	\$ 16,900
O-540-J3A5	YES	ENPL-RT8843	\$ 55,730	C	RENPL-RT8843	\$ 36,542	C	HENPL-RT8843	\$ 32,274	C	\$ 16,900
O-540-J3A5	YES	ENPL-RT9492	\$ 59,296	C	RENPL-RT9492	\$ 39,944	C	HENPL-RT9492	\$ 35,675	C	\$ 16,900
O-540-J3A5D	YES	ENPL-RT6623	\$ 59,831	C	RENPL-RT6623	\$ 40,453	C	HENPL-RT6623	\$ 36,185	C	\$ 16,900
O-540-J3A5D	YES	ENPL-RT8449	\$ 60,217	C	RENPL-RT8449	\$ 40,821	C	HENPL-RT8449	\$ 36,553	C	\$ 16,900
O-540-J3C5D	YES	ENPL-RT8167	\$ 60,915	C	RENPL-RT8167	\$ 40,381	C	HENPL-RT8167	\$ 36,113	C	\$ 16,900
O-540-L3C5D	YES	ENPL-RT8168	\$ 62,209	C	RENPL-RT8168	\$ 42,721	C	HENPL-RT8168	\$ 38,452	C	\$ 16,900
TIO-540-A2B	N/A	ENPL-10252	\$ 94,772	C	RENPL-10252	\$ 68,878	C	HENPL-10252	\$ 62,780	C	\$ 22,000
TIO-540-A2B	N/A	ENPL-8876	\$ 95,086	C	RENPL-8876	\$ 69,177	C	HENPL-8876	\$ 63,080	C	\$ 22,000
TIO-540-A2B	N/A	ENPL-9408	\$ 94,477	C	RENPL-9408	\$ 68,596	C	HENPL-9408	\$ 62,499	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-8269	\$ 95,050	C	RENPL-8269	\$ 69,052	C	HENPL-8269	\$ 62,955	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-8352	\$ 94,893	C	RENPL-8352	\$ 70,142	C	HENPL-8352	\$ 64,044	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-9410	\$ 94,905	C	RENPL-9410	\$ 69,549	C	HENPL-9410	\$ 63,451	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-9411	\$ 94,124	C	RENPL-9411	\$ 68,260	C	HENPL-9411	\$ 62,163	C	\$ 22,000
TIO-540-A2C	N/A	ENPL-9959	\$ 95,065	C	RENPL-9959	\$ 69,157	C	HENPL-9959	\$ 63,059	C	\$ 22,000
TIO-540-AA1AD	N/A	ENPL-8459	\$ 108,132	D	RENPL-8459	\$ 81,617	D	HENPL-8459	\$ 75,519	D	\$ 22,000
TIO-540-AA1AD	N/A	ENPL-8692	\$ 108,256	D	RENPL-8692	\$ 81,735	D	HENPL-8692	\$ 75,638	D	\$ 22,000
TIO-540-AA1AD	N/A	ENPL-8824	\$ 109,102	D	RENPL-8824	\$ 82,542	D	HENPL-8824	\$ 76,444	D	\$ 22,000
TIO-540-AB1AD	N/A	ENPL-7459	\$ 94,572	D	RENPL-7459	\$ 68,687	D	HENPL-7459	\$ 62,590	D	\$ 22,000
TIO-540-AB1AD	N/A	ENPL-8749	\$ 94,431	D	RENPL-8749	\$ 68,553	D	HENPL-8749	\$ 62,455	D	\$ 22,000
TIO-540-AB1BD	N/A	ENPL-8952	\$ 89,830	D	RENPL-8952	\$ 64,166	D	HENPL-8952	\$ 58,068	D	\$ 22,000
TIO-540-AE2A	N/A	ENPL-10033	\$ 125,862	D	RENPL-10033	\$ 98,523	D	HENPL-10033	\$ 92,425	D	\$ 22,000
TIO-540-AE2A	N/A	ENPL-10034	\$ 125,862	D	RENPL-10034	\$ 98,523	D	HENPL-10034	\$ 92,425	D	\$ 22,000
TIO-540-AE2A	N/A	ENPL-10037	\$ 124,569	D	RENPL-10037	\$ 97,291	D	HENPL-10037	\$ 91,193	D	\$ 22,000
TIO-540-AF1B	N/A	ENPL-9906	\$ 96,570	D	RENPL-9906	\$ 70,592	D	HENPL-9906	\$ 64,495	D	\$ 22,000
TIO-540-AG1A	N/A	ENPL-9642	\$ 89,000	D	RENPL-9642	\$ 62,636	D	HENPL-9642	\$ 56,539	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-10125	\$ 108,805	D	RENPL-10125	\$ 82,259	D	HENPL-10125	\$ 76,161	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-10490	\$ 106,378	D	RENPL-10490	\$ 79,945	D	HENPL-10490	\$ 73,847	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-10545	\$ 108,805	D	RENPL-10545	\$ 82,258	D	HENPL-10545	\$ 76,161	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-9660	\$ 108,862	D	RENPL-9660	\$ 82,313	D	HENPL-9660	\$ 76,216	D	\$ 22,000
TIO-540-AH1A	N/A	ENPL-9813	\$ 108,872	D	RENPL-9813	\$ 82,323	D	HENPL-9813	\$ 76,225	D	\$ 22,000
TIO-540-AJ1A	YES	ENPL-RT10249	\$ 114,749	D	RENPL-RT10249	\$ 87,926	D	HENPL-RT10249	\$ 81,829	D	\$ 22,000
TIO-540-AJ1A	YES	ENPL-RT10269	\$ 114,860	D	RENPL-RT10269	\$ 88,032	D	HENPL-RT10269	\$ 81,935	D	\$ 22,000
TIO-540-AJ1A	YES	ENPL-RT10658	\$ 114,233	D	RENPL-RT10658	\$ 87,532	D	HENPL-RT10658	\$ 81,434	D	\$ 22,000
TIO-540-AK1A	N/A	ENPL-10048	\$ 93,332	D	RENPL-10048	\$ 67,505	D	HENPL-10048	\$ 61,407	D	\$ 22,000
TIO-540-AK1A	N/A	ENPL-10385	\$ 93,428	D	RENPL-10385	\$ 67,596	D	HENPL-10385	\$ 61,498	D	\$ 22,000
TIO-540-AK1A	N/A	ENPL-10439	\$ 93,636	D	RENPL-10439	\$ 67,732	D	HENPL-10439	\$ 61,634	D	\$ 22,000
TIO-540-AK1A	N/A	ENPL-10657	\$ 93,040	D	RENPL-10657	\$ 67,281	D	HENPL-10657	\$ 61,183	D	\$ 22,000
TIO-540-C1A	N/A	ENPL-6620	\$ 100,372	D	RENPL-6620	\$ 74,218	D	HENPL-6620	\$ 68,120	D	\$ 22,000
TIO-540-C1A	N/A	ENPL-6621	\$ 100,372	D	RENPL-6621	\$ 74,218	D	HENPL-6621	\$ 68,120	D	\$ 22,000
TIO-540-C1A	N/A	ENPL-8662	\$ 100,387	D	RENPL-8662	\$ 74,232	D	HENPL-8662	\$ 68,135	D	\$ 22,000
TIO-540-F2BD	N/A	ENPL-8198	\$ 95,903	C	RENPL-8198	\$ 69,957	C	HENPL-8198	\$ 63,859	C	\$ 22,000
TIO-540-J2B	N/A	ENPL-10296	\$ 93,559	C	RENPL-10296	\$ 67,775	C	HENPL-10296	\$ 61,678	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-10417	\$ 93,559	C	RENPL-10417	\$ 67,775	C	HENPL-10417	\$ 61,678	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-8120	\$ 93,559	C	RENPL-8120	\$ 67,775	C	HENPL-8120	\$ 61,678	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-8945	\$ 93,559	C	RENPL-8945	\$ 67,775	C	HENPL-8945	\$ 61,678	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-9401	\$ 93,558	C	RENPL-9401	\$ 67,774	C	HENPL-9401	\$ 61,677	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-9606	\$ 94,663	C	RENPL-9606	\$ 68,827	C	HENPL-9606	\$ 62,729	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-10301	\$ 94,459	C	RENPL-10301	\$ 68,633	C	HENPL-10301	\$ 62,535	B	\$ 22,000
TIO-540-J2B	N/A	ENPL-10554	\$ 94,088	C	RENPL-10554	\$ 68,280	C	HENPL-10554	\$ 62,182	B	\$ 22,000

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).

LYCOMING AFTERMARKET ENGINE PRICE LIST  
 Effective January 1, 2012  
 (Prices in U.S. Dollars)

<b>"MSRP" REPRESENTS MANUFACTURES SUGGESTED RETAIL EXCHANGE PRICE</b>											
<b>PLEASE CONTACT THE AUTHORIZED LYCOMING DISTRIBUTOR OF YOUR CHOICE TO OBTAIN SALE PRICES</b>											
ENGINE MODEL	ROLLER TAPPETS	NEW			REBUILT ("ZERO" TIME)			OVERHAUL			CORE VALUE
		PART NO.	MSRP	DC	PART NO.	MSRP	DC	PART NO.	MSRP	DC	
TIO-540-J2BD	N/A	ENPL-8147	\$ 95,609	C	RENPL-8147	\$ 69,057	C	HENPL-8147	\$ 62,959	A	\$ 22,000
TIO-540-S1AD	N/A	ENPL-10279	\$ 96,218	D	RENPL-10279	\$ 70,798	D	HENPL-10279	\$ 64,701	D	\$ 22,000
TIO-540-S1AD	N/A	ENPL-8179	\$ 97,004	D	RENPL-8179	\$ 71,554	D	HENPL-8179	\$ 65,457	D	\$ 22,000
AEIO-580-B1A	YES	ENPL-RT10427	\$ 89,464	D	RENPL-RT10427	\$ 64,322	D	HENPL-RT10427	\$ 58,224	D	\$ 28,200
AEIO-580-B1A	YES	ENPL-RT10568	\$ 89,916	D	RENPL-RT10568	\$ 64,749	D	HENPL-RT10568	\$ 58,652	D	\$ 28,200
AEIO-580-B1A	YES	ENPL-RT10617	\$ 90,560	D	RENPL-RT10617	\$ 65,357	D	HENPL-RT10617	\$ 59,260	D	\$ 28,200
IO-580-B1A	YES	ENPL-RT10462	\$ 94,456	D	RENPL-RT10462	\$ 68,175	D	HENPL-RT10462	\$ 62,077	D	\$ 28,200
TIO-540-S1AD	N/A	ENPL-9426	\$ 96,218	D	RENPL-9426	\$ 70,798	D	HENPL-9426	\$ 64,700	D	\$ 22,000
TIO-540-U2A	N/A	ENPL-8868	\$ 100,203	C	RENPL-8868	\$ 63,606	C	HENPL-8868	\$ 57,508	C	\$ 29,400
TIO-540-U2A	N/A	ENPL-8894	\$ 101,986	C	RENPL-8894	\$ 65,305	C	HENPL-8894	\$ 59,208	C	\$ 29,400
IO-720-A1B	N/A	ENPL-7356	\$ 132,202	D	RENPL-7356	\$ 82,692	D	HENPL-7356	\$ 73,545	D	\$ 40,300
IO-720-A1B	N/A	ENPL-7371	\$ 135,717	D	RENPL-7371	\$ 86,042	D	HENPL-7371	\$ 76,896	D	\$ 40,300
IO-720-A1B	N/A	ENPL-7491	\$ 134,124	D	RENPL-7491	\$ 84,524	D	HENPL-7491	\$ 75,378	D	\$ 40,300
IO-720-A1B	N/A	ENPL-8546	\$ 134,300	D	RENPL-8546	\$ 84,692	D	HENPL-8546	\$ 75,546	D	\$ 40,300
IO-720-B1B	N/A	ENPL-9578	\$ 130,170	D	RENPL-9578	\$ 80,753	D	HENPL-9578	\$ 71,607	D	\$ 40,300
IO-720-D1B	N/A	ENPL-7488	\$ 136,518	D	RENPL-7488	\$ 86,807	D	HENPL-7488	\$ 77,660	D	\$ 40,300
IO-720-D1C	N/A	ENPL-7218	\$ 133,709	D	RENPL-7218	\$ 84,128	D	HENPL-7218	\$ 74,982	D	\$ 40,300
TIO-540-U2A	N/A	ENPL-9663	\$ 101,986	C	RENPL-9663	\$ 65,305	C	HENPL-9663	\$ 59,208	C	\$ 29,400
TIO-540-U2A	N/A	ENPL-9872	\$ 102,302	C	RENPL-9872	\$ 65,607	C	HENPL-9872	\$ 59,509	C	\$ 29,400
TIO-540-W2A	N/A	ENPL-9434	\$ 125,825	D	RENPL-9434	\$ 88,037	D	HENPL-9434	\$ 81,939	D	\$ 29,400

DC = Delivery/Return/Cancellation Code  
 \*\* = New Cam  
 \*\*\* = New Rods \*\*\*\* = Top End Chrome  
 Domestic Freight - 4 cyl \$159  
 Domestic Freight - 6 cyl \$219  
 New Outright price equals (new exchange price X 1.2).



A Textron Company

---

## WARRANTY NEW AND REBUILT ENGINES

(1) **WARRANTY AND REMEDY:** Lycoming Engines, a division of Avco Corporation (hereinafter "Lycoming") warrants each new and rebuilt Lycoming reciprocating engine to be free from defect in material or workmanship under normal use and service. Lycoming's sole obligation under this warranty is limited to replacement or repair of parts which are determined by Lycoming to have been defective within a period of twenty-four (24) months after new aircraft delivery to the original retail purchaser or first user, or twenty-four (24) months from the date of first operation. The warranty period of twenty-four (24) months commences on the earlier of the date of first operation after new aircraft delivery to the original retail purchaser or first user, or twenty-four (24) months from the date of shipment from Lycoming. Lycoming will, in connection with the foregoing warranty, cover reimbursement of reasonable freight charges with respect to any such warranty replacement or repair.

(2) Within the warranty period, Lycoming will reimburse the Purchaser for labor charges associated with warranty related issues. Lycoming will only reimburse the cost of such labor charges in connection with repair or replacement of parts as provided in Lycoming's then current Removal and Installation Labor and Allowance Guidebook. Spare parts installed as warranty replacement on engines which are covered by this New Engine Warranty will be warranted for the balance of the original warranty period or for the spare part warranty, whichever is the greater. Replacement of parts may be with either new or reconditioned parts, at Lycoming's election. A claim for warranty on any part claimed to be defective must be reported in writing to Lycoming's Warranty Administration within 60 days of being found to require repair or replacement by the purchaser or service facility. Warranty adjustment is contingent upon the Purchaser complying with the Lycoming's Warranty Administration disposition instructions for defective parts. Failure to comply with all of the terms of this paragraph may, at Lycoming's sole option, void this warranty.

(3) THIS WARRANTY IS GIVEN AND ACCEPTED IN PLACE OF (i) ALL OTHER WARRANTIES OR CONDITIONS, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE IMPLIED WARRANTIES OR CONDITION OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE AND (ii) ANY OBLIGATION, LIABILITY, RIGHT, CLAIM OR REMEDY IN CONTRACT OR IN TORT (DELICT), INCLUDING PRODUCT LIABILITIES BASED UPON STRICT LIABILITY, NEGLIGENCE, OR IMPLIED WARRANTY IN LAW AND PURCHASER HEREBY WAIVES SUCH RIGHTS AND CLAIMS.

(4) THIS WARRANTY IS THE ONLY WARRANTY MADE BY LYCOMING. THE PURCHASER'S SOLE REMEDY FOR A BREACH OF THIS WARRANTY OR ANY DEFECT IN A PART IS THE REPAIR OR REPLACEMENT OF ENGINE PARTS AND REIMBURSEMENT OF REASONABLE FREIGHT CHARGES AS PROVIDED HEREIN. LYCOMING EXCLUDES LIABILITY, WHETHER AS A RESULT OF A BREACH OF CONSEQUENTIAL DAMAGES, INCLUDING, BUT NOT LIMITED TO, DAMAGE TO THE ENGINE OR OTHER PROPERTY (INCLUDING THE AIRCRAFT IN WHICH THE ENGINE IS INSTALLED), COSTS AND EXPENSES RESULTING FROM REQUIRED CHANGES OR MODIFICATIONS TO ENGINE COMPONENTS AND ASSEMBLIES, CHANGES IN RETIREMENT LIVES AND OVERHAUL PERIODS, LOCAL CUSTOMS FEES AND TAXES, AND COSTS OR EXPENSES FOR COMMERCIAL LOSSES OR LOST PROFITS DUE TO LOSS OF USE OR GROUNDING OF THE AIRCRAFT IN WHICH THE ENGINE IS INSTALLED OR OTHERWISE. LYCOMING'S TOTAL LIABILITY FOR ANY AND ALL CLAIMS RELATED TO ANY ENGINE SHALL IN NO CASE EXCEED THE ORIGINAL SALES PRICE OF THE ENGINE. SELLER MAKES NO WARRANTY AND DISCLAIMS ALL LIABILITY WITH RESPECT TO COMPONENTS OR PARTS DAMAGED BY, OR WORN DUE TO, CORROSION.

# **LYCOMING**

A Textron Company

(5) This warranty shall not apply to any engine or part thereof which has been repaired or altered outside Lycoming's factory in any way so as, in Lycoming's sole judgment, to affect its durability, safety or reliability, or which has been subject to misuse, negligence or accident. Repairs and alterations which use or incorporate parts and components other than genuine Lycoming parts or parts approved by Lycoming for direct acquisition from sources other than Lycoming itself are not warranted by Lycoming, and this warranty shall be void to the extent that such repairs and alterations, in Lycoming's sole judgment, affect the durability, safety or reliability of the engine or any part thereof, or damage genuine Lycoming or Lycoming-approved parts. No person, corporation or organization, including Distributors of Lycoming engines, is authorized by Lycoming to assume for it any other liability in connection with the sale of its engines or parts, nor to make any warranties beyond the foregoing warranty nor to change any of the terms hereof. NO STATEMENT, WHETHER WRITTEN OR ORAL, MADE BY ANY PERSON, CORPORATION OR ORGANIZATION, INCLUDING DISTRIBUTORS OF LYCOMING ENGINES MAY BE TAKEN AS A WARRANTY NOR WILL IT BIND LYCOMING. NO AGREEMENT VARYING THE TERMS OF THIS WARRANTY OR LYCOMING'S OBLIGATIONS UNDER IT IS BINDING UPON LYCOMING UNLESS IN WRITING AND SIGNED BY A DULY AUTHORIZED REPRESENTATIVE OF LYCOMING.

(6) All legal actions based upon claims or disputes pertaining to or involving this warranty including, but not limited to, Lycoming's denial of any claim or portion thereof under this warranty, must be filed in the courts of general jurisdiction of Lycoming County, Commonwealth of Pennsylvania or in the United States District Court for the Middle District of Pennsylvania located in Williamsport, Pennsylvania. In the event that Purchaser files such an action in either of the court systems identified above, and a final judgment in Lycoming's favor is rendered by such court, then Purchaser shall indemnify Lycoming for all costs, expenses and attorneys' fee incurred by Lycoming in defense of such claims. In the event Purchaser files such a legal action in a court other than those specified, and Lycoming successfully obtains dismissal of that action or transfer thereof to the above described court systems, then Purchaser shall indemnify Lycoming for all costs, expenses and attorneys' fees incurred by Lycoming in obtaining such dismissal or transfer.

(7) Any invalidity of a provision of this Warranty shall not affect any other provision, and in the event of a judicial finding of such invalidity, this Agreement shall remain in force in all other respects.

*Effective April 2007 Revision "N"*

**Lycoming Engines**  
652 Oliver Street  
Williamsport, Pennsylvania  
17701  
(570) 323-6181  
[www.lycoming.com](http://www.lycoming.com)





A Textron Company

---

WARRANTY  
(LIMITED)  
OVERHAULED  
RECIPROCATING AIRCRAFT ENGINE

WHAT LYCOMING PROMISES YOU

Lycoming warrants each overhauled reciprocating engine sold by it to be free from defects in material and workmanship for a period of twelve (12) months from date of first operation. Cylinders are warranted for a period of twenty-four (24) months\*. The date of first operation must not exceed two (2) years from the date of shipment from Lycoming.

Lycoming's obligation under this warranty shall be limited to its choice of repair or replacement, on an exchange basis, of the engine or any part of the engine, when Lycoming has determined that the engine is defective in material or workmanship. Such repair or replacement will be made by Lycoming at no charge to you. Lycoming will also bear the cost for labor in connection with the repair or replacement as provided in Lycoming's then current Removal and Installation Labor Allowance Guidebook.

Any engine or part so repaired or replaced will be entitled to warranty for the remainder of the original warranty period.

YOUR OBLIGATIONS

The engine must have received normal use and service. You must apply for warranty with an authorized Lycoming distributor within 30 days of the appearance of the defect in material or workmanship.

Lycoming's warranty does not cover normal maintenance expenses or consumable items. The obligations on the part of Lycoming set forth above are your exclusive remedy and the exclusive liability of Lycoming. This warranty allocates the risk of product failure between you and Lycoming, as permitted by applicable law.

Lycoming reserves the right to deny any warranty claim if it reasonably determines that the engine or part has been subject to accident or used, adjusted, altered, handled, maintained or stored other than as directed in your operator's manual, or if non-genuine Lycoming parts are installed in or on the engine and are determined to be a possible cause of the incident for which the warranty application is filed.

Lycoming may change the construction of engines at any time without incurring any obligation to incorporate such alterations in engines or parts previously sold.

\*Excludes O-235 series cylinders that have the same warranty as the engine.

# **LYCOMING**

A Textron Company

---

THIS LIMITED WARRANTY IS EXCLUSIVE AND IN LIEU OF ALL OTHER WARRANTIES AND REPRESENTATIONS, EXPRESS OR IMPLIED OR STATUTORY, WHETHER WRITTEN OR ORAL, INCLUDING BUT NOT LIMITED TO ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR ANY PARTICULAR PURPOSE, AND ANY IMPLIED WARRANTY ARISING FROM ANY COURSE OF PERFORMANCE OR DEALING OR TRADE USAGE. THIS WARRANTY IS ALSO IN LIEU OF ANY OTHER OBLIGATION, LIABILITY, RIGHT OR CLAIM, WHETHER IN CONTRACT OR IN TORT, INCLUDING ANY RIGHT IN STRICT LIABILITY IN TORT OR ANY RIGHT ARISING FROM NEGLIGENCE ON THE PART OF LYCOMING, AND LYCOMING'S LIABILITY ON SUCH CLAIM SHALL IN NO CASE EXCEED THE PRICE ALLOCABLE TO THE ENGINE OR PART WHICH GIVES RISE TO THE CLAIM.

## LIMITATION OF LIABILITY

IN NO EVENT, WHETHER AS A RESULT OF A BREACH OF WARRANTY, CONTRACT OR ALLEGED NEGLIGENCE, SHALL LYCOMING BE LIABLE FOR SPECIAL OR CONSEQUENTIAL OR ANY OTHER DAMAGES, INCLUDING BUT NOT LIMITED TO LOSS OF PROFITS OR REVENUES, LOSS OF USE OF THE ENGINE OR COST OF A REPLACEMENT.

No agreement varying this warranty or Lycoming's obligations under it will be binding upon Lycoming unless in writing signed by a duly authorized representative of Lycoming.

*Effective March 2002 Revision "K"*

**Lycoming Engines**  
652 Oliver Street  
Williamsport, Pennsylvania  
17701  
(570) 323-6181  
[www.lycoming.com](http://www.lycoming.com)

